



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD  
#48-01 MARINA BAY FINANCIAL CENTRE TOWER  
2SINGAPORE 018983

Ref: CS/HSB23002548/Aqy3

Date: 10/03/2023

Code: HSB

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 102D	Veh. Inspected	SCR 76B
Policy No.		Coverage (\$)	0.00
Claim No.	S3M04KAQ	Excess (\$)	0.00
Assign From	KHOR SAW THENG	Assign Date	10/03/2023

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	08/03/2023	Inspection Date	10/03/2023
Survey held at	TSL AUTO GARAGE BLK 1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--