

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0249/2023/EQ
DATE : 6-Mar-23
WIP : 10280

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 8/3/2023

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR LIM KAR HENG DENNIS
ADDRESS : 50 CHOA CHU KANG NORTH 7
#06-09
SINGAPORE 689527
TELEPHONE : HP +65 96975588
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210027627
VEHICLE NO : **SLV 4898 S**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 19/3/2021
ENGINE NO : DEM 025395
CHASSIS NO : WAUZZZF45MN000903
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : JALAN EUNOS TOWARDS ECP BEFORE JALAN KECHOT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLV 4898 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00 ?	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ?	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,900.00 1500 (Without lock carrier)	
6	TO RESPRAY FRONT BUMPER, BONNET AND RHS FRONT FENDER.	\$ 3,000.00 1650 2750 (With lock carrier)	
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 11,522.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Debond</i>	1	\$	2,515.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$	416.00	+
3	FRONT BUMPER SECURING STRIP - LH / RH ?	2	\$	84.00	?
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$	231.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$	310.00	+
6	FRONT BUMPER AIR GUIDE - LH / RH <i>RH → new</i>	2	\$	166.00	+
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE ?	1	\$	310.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - RH ?	1	\$	159.00	?
9	FRONT BUMPER OUTER GRILLE HOLE COVER - RH <i>new</i>	1	\$	57.00	+
10	RADIATOR GRILLE <i>Cracked</i>	1	\$	1,861.00	✓
11	FRONT BUMPER FOAM FILLER PIECE ?	1	\$	224.00	?
12	FRONT BUMPER TOP COVER ?	1	\$	151.00	?
13	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$	86.00	+
14	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$	953.00	?
15	FRONT BUMPER BRACKET - RH ?	1	\$	269.00	?
16	CAUTION SIGN STICKER ?	1	\$	17.00	?
17	AIR CONDITIONER STICKER ?	1	\$	9.00	?
18	FRONT BUMPER BRACKET ?	1	\$	163.00	?
19	FRONT BUMPER SUPPORT - LH / RH ?	2	\$	68.00	?
20	HORN LOW TONE - RH <i>new</i>		\$	149.00	+
SUB TOTAL SPARE PARTS		:	\$	8,198.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - RH <i>new</i>	1	\$ 35.00	X
22	FRONT PARKING AID SENSOR - INNER / OUTER <i>not new</i>	2	\$ 544.00	+
23	FRONT PARKING AID SEAL RING } <i>new</i>	4	\$ 11.00	+
24	FRONT BUMPER WIRNG SET	1	\$ 648.00	+
25	FRONT FENDER - RH <i>Buckled</i>	1	\$ 1,299.00	✓
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 238.00	+
27	FRONT FENDER CLOSING ELEMENT - RH } <i>new</i>	1	\$ 86.00	+
28	FRONT FENDER BRACKET - RH	1	\$ 44.00	+
29	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH <i>new</i>	1	\$ 59.00	+
30	FRONT FENDER RIVET <i>new</i>	7	\$ 28.00	✓
31	FRONT FENDER BRACE - RH <i>new</i>	1	\$ 140.00	X
32	FRONT WHEEL HOUSING LINER <i>new</i>	1	\$ 277.00	+
33	FRONT WHEEL SPOILER <i>new</i>	1	\$ 87.00	+
34	FRONT WHEEL SPOILER END PLATE - RH <i>new</i>	1	\$ 43.00	+
35	FRONT FENDER LEDGE COVER - RH ?	1	\$ 37.00	?
36	HEADLAMP COVER - RH ?	1	\$ 52.00	?
37	BONNET <i>Dented</i>	1	\$ 3,489.00	✓
38	BONNET ATTACHMENT PARTS <i>Not new</i>	1	\$ 455.00	X
39	BONNET HINGE - LH / RH <i>Not new</i>	2	\$ 722.00	X
40	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>new</i>	3	\$ 101.00	✓
SUB TOTAL SPARE PARTS		:	\$ 8,395.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET STRIKER - LH / RH <i>Not New</i>	2	\$ 120.00	X
42	BONNET LOCK - LH / RH ?	2	\$ 481.00	?
43	BONNET BOWDEN CABLE - CENTER	1	\$ 67.00	X
44	BONNET RELEASE CABLE COVER	1	\$ 12.00	X
45	BONNET BOWDEN CABLE - CENTER <i>Not New</i>	1	\$ 67.00	X
46	BONNET RELEASE LEVER	1	\$ 16.00	X
47	BONNET LOCK CABLE	1	\$ 87.00	X
48	HEADLIGHT - RH <i>Cracked</i>	1	\$ 8,666.00	✓
49	HEADLIGHT HOSE <i>New</i>	1	\$ 43.00	X
50	LIFT CYLINDER - RH <i>New</i>	1	\$ 244.00	X
51	LIFT CYLINDER BRACKET	1	\$ 8.00	X
52	LIFT CYLINDER CORRUGATED PIPE <i>Not New</i>	1	\$ 111.00	X
53	LIFT CYLINDER CORRUGATED PIPE <i>New</i>	1	\$ 55.00	X
54	LOCK CARRIER ?	1	\$ 1,569.00	?
55	LOCK CARRIER SUPPORT ?	1	\$ 45.00	?
56	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 22.00	?
57	A/C CONDENSER <i>Not New</i>	1	\$ 724.00	X
58	CHARGE AIR COOLER	1	\$ 692.00	X
59	CHARGE AIR COOLER PRESSURE HOSE - RH <i>New</i>	1	\$ 412.00	X
60	READY-MIX COOLANT ?	6	\$ 326.00	?
SUB TOTAL SPARE PARTS			\$ 13,767.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLV 4898 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR AIR GUIDE - LH / RH INNER	2	\$ 76.00	?
62	RADIATOR AIR GUIDE - LH / RH OUTER	2	\$ 50.00	?
63	RADIATOR AIR GUIDE - UPPER ?	1	\$ 25.00	?
64	RADIATOR AIR GUIDE - LOWER ?	1	\$ 38.00	?
65	RADIATOR INTAKE AIR DUCT - RH LOWER ?	1	\$ 38.00	?
66	RADIATOR AIR GUIDE - CENTER ?	1	\$ 67.00	?
67	RADIATOR INTAKE HOSE - UPPER ?	1	\$ 114.00	?
68	RADIATOR AIR FILTER	1	\$ 443.00	X
69	AIR MASS METER	1	\$ 639.00	X
70	FRONT NUMBER PLATE Dented	S/N	\$ 60.00	✓
71	SUNDRIES ?		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 32,310.00	
TOTAL LABOUR CHARGES		:	\$ 11,522.00	
GRAND TOTAL		:	\$ 43,832.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian King,
10/03/03

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 05 Days (Without Lock Carrier)
08 Days (With Lock Carrier)

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT