

Your Ref: DV.2021.223068

Date: 14th Mar 2023

Our Ref: CS1/LAW23002557/Dqy3e2

M/s Comlaw LLC

64 Cecil St #06-01 IOB BLDG

Singapore 049711

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBC 5646P
INSURED VEHICLE: SHC 5854J
ACCIDENT DATE: 17/05/2020**

We thank you for your instruction on 24/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBC 5646P from M/s Advanced Automotive Consultancy Pte Ltd.
- b) Final Repair Bill of FBC 5646P from M/s Equator Brotherhood.
- c) Singapore Accident Statement and Police Report of Vehicles FBC 5646P and SHC 5854J.
- d) Colour damaged vehicle photographs of FBC 5646P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBC 5646P
Make & Model	: Yamaha T135
Chassis Number	: 5YP208632
Year of Registration	: 2008
Engine Capacity	: 135 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.