

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305547999

Date : 09 03 23

Time of Fax : _____

Via Fax : Email

Your Insured : SNC 8821M

Date of Acc : 09 03 23

Attn: Motor Claims Department

Allianz

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D4781L

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ Juman Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **limts@cdge.com.sg**
Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

Lim Tien Siong

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATEDATE: 09.03.2023INSURANCE: ALLIANZMODEL: Hyundai IoniqSURVEYOR: NAVEHICLE NO.: SHD4781LMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket RH	1		\$ 138.10
	Rear Bumper Side Brackets RH	1		\$ 55.80
	Rear Bumper Centre Moulding	1		\$ 451.25
	Rear Bumper Lower Centre Moulding	1		\$ 155.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Side Under Cover RH	1		\$ 108.00
	Rear Bumper Reflector Lamp RH	1		\$ 41.45
	Rear Bumper Tow Cover	1		\$ 98.80
	Rear Bumper FogLamp	1		\$ 201.50
	Rear Smart Key Antenna	1		\$ 40.50
	TailLamp RH	1		\$ 935.40
	SUB TOTAL			\$ 3,102.00
	LESS 25%			\$ 775.50
	DISCOUNTED TOTAL			\$ 2,326.50
	Rear Bumper Mat	1		\$ 50.00
	Reverse Sensors	1		\$ 180.00
	Rear No.Plate With Trim Cover	1		\$ 55.00
	S/NETT TOTAL			\$ 285.00
	SPARE PARTS TOTAL			\$ 2,611.50
	<u>Labour Charge</u>			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Check Lightings			\$ 40.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 860.00
	ESTIMATE TOTAL			\$ 3,471.50

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.