

Taught

ASSIGNMENT

Date: _____ Person Contacted: _____

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop: or
Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

TOTAL



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNJ1955U

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **63514**
Reg No/Reg Date **SNJ1955U / 28/12/2022**
Date In/Mileage **/ 0**
Chassis No **W1N2477842J4518556**
Engine No **28291480925738**
Make/Model **MB/GLA 180**
Colour/Trim **026 667 Denim Blue / 046 651 Black**

Account No	Terms	Date/Time Printed	CSE	Operator	
WL001605	Credit	10/03/2023/ 08:57	K0	301 / Kerlyn Ong	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

Z REQUEST

Customer Request
M BPNSUN

POLICY NO/ACC DATE : SP2003907937 // 08/03/2023
DRIVE IN/TP VEHICLE NO : 09/03/2023 // GBA7068E -
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER & LH/ FRONT FENDER

A BPILAB

USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO
IDENTIFICATION STANDARD. NETT

A BPILAB

TO REMOVE, REPLACE HEADLAMP WITH FOCUS . NETT

M FRONT BUMPER

1.00 1479.47 00.00

M LH/ FRONT BUMPER LOWER TRIM

1.00 71.44 00.00

M LH/ FRONT BUMPER MOUNTING RAIL

1.00 9.33 00.00

M LH/ FRONT FENDER TRIM

1.00 227.85 00.00

M LH/ FRONT FENDER EDGE GUARD

1.00 20.58 00.00

M LH/ HEADLAMP UNIT

1.00 3097.36 00.00

3097.36

\$6637.36

850 1440
1920.00
xxx 1600
1800.00
0.10 ✓ 380.00
✓ 120.00
3540
Ry 1479.47
nn x 71.44
nn x 9.33
nn x 227.85
nn x 20.58
nn ✓ 3097.36

Tanfah 97495749/6256356
wip 6/4/23 13:50pm
p/p Resurvey new parts.
tanfah@lhaauto.com
3 days

Kerlyn Ong Kai Li
DID : 6771 4420 HP : 9186 5113
Email : kerlyn.ong@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

LKK Auto Consultants hence notify
the Reprsir of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and

Authorized signatory and company stamp

8% GST on **Nett 9,126.03**
9126.03 730.08
Total Payable 9,856.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document. No signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg