

A.S. P.C. BY:

REF:

CC4/AIS 2300 2563/Dpa³

ASSIGNMENT

COE Jan 2028

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 9 days Res.: Yes or NoLum Sum: 10 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 841D 47512 Yr Regn: Jan / 2020

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ionix CC 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 283108 T/Radio: Insured / Std / NI / NAEng/No: G4LEKU404654C/No: KMHLC852CVLW188803

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A. 04/03/2023 D.O.I. 09/03/2023Survey held at 31 Frost sin King

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Allianz YP 2907 R17/7/23propose L/S 14,750/- with 9 days of repair

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐: Prel. Report☐: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS: \$

Photos

Others

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inve (\$)

Report Format: _____

I certify I have read & understand the contents of this report.

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 6-Mar-23

INSURANCE: Allianz

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHD 4751 Z

Description	Qty	List Price	Amount
Boot Lid <i>Denial</i>	1	\$ 2,549.70	\$ 2,549.70
Boot Lid Rubber <i>damaged</i>	1	\$ 187.40	\$ 187.40
Boot Lid Hinge (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40
Boot Lid Lock Upper <i>Denial</i>	1	\$ 224.00	\$ 224.00
Boot Lid 'H' Emblem <i>HH</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HH</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>HH</i>	1	\$ 31.30	\$ 31.30
Rear Spoiler <i>broken</i>	1	\$ 665.40	\$ 665.40
Third Brake Light <i>crack</i>	1	\$ 385.60	\$ 385.60
BOOT HANDLE <i>HH</i>	1	\$ 31.80	\$31.80
Boot Lid Lamp(LH/RH) <i>crack</i>	2	\$ 822.00	\$ 1,644.00
Boot Lid Trimboard <i>mostly broken</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>HH</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>mostly crack</i>	1	\$ 159.60	\$ 159.60
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	2	\$ 92.50	\$ 185.00
Boot Lid Trimboard REAR <i>HH</i>	1	\$ 124.80	\$ 124.80
Boot Lid Glass, Lower <i>shattered</i>	1	\$ 584.90	\$ 584.90
Boot Lid Glass Upper Moulding <i>HH</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HH</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>Denial</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Reinforcement <i>broken</i>	1	\$ 394.80	\$ 394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>Denial</i>	2	\$ 188.10	\$ 376.20
Antenna Assy-SMARTK outer <i>mostly broken</i>	1	\$ 689.50	\$ 689.50

✓
✓
X
X
✓
✓
✓
✓
✓
✓
X
✓
✓
X
X
✓
X
X
✓
✓
✓
✓

Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25
Rear Bumper Lower Centre Moulding Assy <i>scr</i>	1	\$ 155.00	\$ 155.00
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10
Rear Bumper Side retainer (LH/RH) <i>HH</i>	2	\$ 85.80	\$ 171.60
Rear Bumper Cover Clips <i>HH</i>	1	\$ 22.00	\$ 22.00
Rear Bumper Under Centre <i>scr</i>	1	\$ 123.85	\$ 123.85
Rear Bumper Side Under(LH/RH) <i>o/s HH u/s broken</i>	2	\$ 123.10	\$ 246.20
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>	2	\$ 82.90	\$ 165.80
Rear Bumper Towing Cover <i>HH</i>	1	\$ 98.80	\$ 98.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket broken</i>	1	\$ 328.60	\$ 328.60
Licence Lamp <i>mainly broken</i>	1	\$ 193.53	\$ 193.53
Tail Lamp(LH/RH) <i>mainly broken</i>	2	\$ 935.40	\$ 1,870.80
Tail Lamp Quarter Panel(LH/RH) <i>o/s HH u/s HH</i>	2	\$ 208.90	\$ 417.80
Rear Panel <i>Deaf</i>	1	\$ 532.00	\$ 532.00
Antenna Assy - TRUNK <i>mainly broken</i>	1	\$ 689.50	\$ 689.50
Rear Panel Garnish <i>mainly deformed</i>	1	\$ 346.80	\$ 346.80
Spare Tyre Holder <i>HH</i>	1	\$ 223.10	\$ 223.10
Spare Wheel Lock Nut <i>HH</i>	1	\$ 89.50	\$ 89.50
Spare Tyre Panel <i>HH</i>	1	\$ 892.50	\$ 892.50
Spare Tyre Panel Cushion <i>HH</i>	1	\$ 692.50	\$ 692.50
Rear tray tools box RH <i>deformed</i>	1	\$ 675.30	\$ 675.30
Rear tray tools box LH <i>broken</i>	1	\$ 693.20	\$ 693.20
REAR TRAY LUGGS CENTER <i>deformed</i>	1	\$ 354.20	\$ 354.20
Exhaust Pipe Insulator <i>HH</i>	1	\$ 235.00	\$ 235.00
Exhaust Silencer <i>HH</i>	1	\$ 943.50	\$ 943.50
Exhaust Pipe Hanger <i>HH</i>	1	\$ 29.20	\$ 29.20
Assy BSD Blind Spot Radar (LH/RH) <i>o/s HH u/s HH</i>	2	\$ 1,784.40	\$ 3,568.80
SUB TOTAL			\$ 24,106.93
LESS 20%			\$ 4,821.39
DISCOUNTED TOTAL			\$ 19,285.54
Reverse camera ASSY <i>HH</i>	SN 1	\$ 983.20	\$ 983.20
Boot Lid Comfort Logo & Tel No. Sticker <i>HH</i>	SN 1	\$ 35.00	\$ 35.00

✓
X
X
X
✓
X
✓
X
X
X
✓
✓
✓
✓
X
✓
✓
X
X
X
✓
✓
✓
✓
X
X
X
✓

17,420.98
13,936.78
X
✓

Boot Lid Comfort Cablink Tel No. Sticker	Hec	SN	1	\$ 30.00	\$ 30.00
Boot Lid Advertisement Logo	Hec	SN	1	\$ 100.00	\$ 100.00
Rear No.Plate + Trim Cover	dishlodged/broken	SN	1	\$ 45.00	\$ 45.00
Rear Windscreen Sealant	Hec	SN	2	\$ 46.00	\$ 92.00
Rear Bumper Advertisement Logo	Hec	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Rubber Mat	Hec	SN	1	\$ 50.00	\$ 50.00
Rear Bumper Reverse Sensor	Demo	SN	1	\$ 180.00	\$ 180.00
SPARE TYRE PANEL TOP COVER SILICON	Hm	SN	1	\$ 250.00	\$ 250.00
SUB TOTAL					\$ 1,815.20
Labour Charge					
Panel Beating			1	\$1,800.00	\$1,800.00
Spray Painting Charge			1	\$1,600.00	\$1,600.00
Wiring Charge			1	\$100.00	\$100.00
Tuff Kote			1	\$100.00	\$100.00
Towing Charge			1	\$80.00	\$80.00
Remove/Refix Rear Windscreen Glass			2	\$120.00	\$240.00
Remove/Refix Exhaust Pipe			1	\$80.00	\$80.00
Diagnostic & Resetting To Erase Fault Code			1	\$550.00	\$550.00
Diagnostic & Resetting ADAS Optical sensor			1	\$550.00	\$550.00
TOTAL LABOUR					\$5,100.00
ESTIMATE TOTAL					\$26,200.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com					

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	821R

Vehicle Details

Vehicle No.:	SHD4751Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	31 Mar 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU404654
Chassis No.:	KMHC851CVLU188803
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,238.00
Original Registration Date:	23 Jan 2020
First Registration Date:	23 Jan 2020
Transfer Count:	0
Actual ARF Paid:	\$12,334.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jan 2028
PARF Rebate Amount:	\$9,250.00

Intended COE Rebate Details

COE Expiry Date:	22 Jan 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$25,895.00
COE Rebate Amount:	\$15,566.00
Total Rebate Amount:	\$24,816.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Mar 2023

OK