

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 27.02.2023

TO : AIG MOTOR CLAIMS DEPTS
VEHICLE NO : SLE2911P
MODEL : HONDA SHUTTLE
DATE OF ACCIDENT : 26.02.2023
TIME OF ACCIDENT : 15:50 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Delud</i>	1	\$ 1,280.00	\$ 1,280.00 <i>85</i>
2	REAR BUMPER EXHAUST COVER GARNISH <i>new</i>	1	\$ 57.00	\$ 57.00
3	REAR BUMPER REFLECTOR <i>3 new</i>	2	\$ 49.00	\$ 98.00
4	REAR BUMPER REFLECTOR GARNISH	2	\$ 68.00	\$ 136.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 19.00	\$ 19.00
6	REAR BUMPER SPONGE <i>2H could</i>	2	\$ 47.00	\$ 94.00 <i>47</i>
7	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 32.00	\$ 64.00
8	TAIL GATE <i>Tested new</i>	1	\$ 1,400.00	\$ 1,400.00 <i>1193</i>
9	TAIL GATE OUTER GARNISH CW MOULDING (CHROME)	1	\$ 695.00	\$ 695.00
10	TAIL GATE NUMBER PLATE LAMP <i>new</i>	2	\$ 38.00	\$ 76.00
11	TAIL GATE LOGO <i>new</i>	1	\$ 45.00	\$ 45.00
12	TAIL GATE EMBLEM " SHUTTLE" <i>new</i>	1	\$ 70.00	\$ 70.00
13	TAIL GATE LAMP <i>new</i>	2	\$ 395.00	\$ 790.00
14	TAIL GATE DAMPER <i>2</i>	2	\$ 125.00	\$ 250.00
15	TAIL GATE HINGE <i>1/4</i>	2	\$ 50.00	\$ 100.00
16	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 40.00	\$ 40.00
17	TAIL GATE STOPPER	2	\$ 25.00	\$ 50.00
18	TAIL GATE INNER LOCK <i>2 new</i>	1	\$ 190.00	\$ 190.00
19	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 24.00	\$ 24.00
20	TAIL GATE WEATHER STRIP <i>cut</i>	1	\$ 190.00	\$ 190.00

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SLE2911P
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 26.02.2023
 TIME OF ACCIDENT : 15:50 HOURS

21	TAIL GATE DETECTOR <i>Not ne</i>	1	\$	296.00	\$	296.00	+
22	TAIL GATE DETECTOR WIRE HARNESS <i>ne</i>	1	\$	586.00	\$	586.00	+
23	TAIL GATE INNER TRIM <i>could</i>	1	\$	320.00	\$	320.00	✓
24	TAIL GATE WINDSCREEN MOULDING <i>ne</i>	1	\$	160.00	\$	160.00	✓
25	REAR BUZZER <i>ne</i>	1	\$	170.00	\$	170.00	+
26	REAR BUZZER WIRE HARNESS <i>ne</i>	1	\$	285.30	\$	285.30	+
27	TAIL LAMP <i>RH could RH</i>	2	\$	520.00	\$	1040.00	520
28	TAIL LAMP LOWER PANEL (OUTER) <i>ne Dented</i>	2	\$	272.00	\$	544.00	272
29	REAR FENDER COWLING <i>ne ne</i>	2	\$	147.00	\$	294.00	+
30	REAR FENDER INNER TRIM <i>near RH could</i>	2	\$	550.00	\$	1100.00	395.
31	REAR END PANEL <i>Dented.</i>	1	\$	920.00	\$	920.00	615.
32	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$	155.00	\$	155.00	✓
33	REAR FLOOR PANEL TOP OUTER COVER BOARD <i>Dented</i>	1	\$	585.00	\$	585.00	✓
34	REAR FLOOR PANEL TOP SIDE COVER BOARD <i>3rd Jan</i>	2	\$	150.00	\$	300.00	+
35	REAR FLOOR PANEL TOP INNER COVER BOARD	1	\$	340.00	\$	340.00	+
36	REAR STORAGE BOX (SPONGE) <i>ne</i>	1	\$	250.00	\$	250.00	+
37	REAR STORAGE BOX (PLASTIC) <i>could</i>	1	\$	495.00	\$	495.00	✓
38	REAR TOOLS SPONGE TRAY <i>ne</i>	1	\$	185.00	\$	185.00	+
39	REAR JACK COVER GARNISH <i>ne ne</i>	1	\$	190.00	\$	190.00	+
40	REAR JACK <i>ne ne</i>	1	\$	145.00	\$	145.00	+

6192
 4953.60

TOTAL PRICE \$ 14,028.30
 LESS 20% \$ 2,805.66
 SUB TOTAL PRICE \$ 11,222.64

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not Rec</i>	1	\$ 120.00	\$ 120.00
2	REAR BUMPER CLIP (SET) <i>Not Rec</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>Not Rec</i>	1	\$ 30.00	\$ 30.00
4	TAIL GATE INNER TRIM CLIP (SET) <i>Not Rec</i>	1	\$ 80.00	\$ 80.00
5	TAIL GATE WINDSCREEN SEALANT <i>Not Rec</i>	1	\$ 80.00	\$ 80.00
6	TAIL GATE WINDSCREEN INNER SEAL <i>Not Rec</i>	1	\$ 60.00	\$ 60.00
7	TAIL GATE WINDSCREEN INNER SOLAR FILM <i>Not Rec</i>	1	\$ 550.00	\$ 550.00
8	TAIL LAMP CLIP (SET) <i>Not Rec</i>	1	\$ 60.00	\$ 60.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLE2911P**
 MODEL : **HONDA SHUTTLE**
 DATE OF ACCIDENT : 26.02.2023
 TIME OF ACCIDENT : 15:50 HOURS

9	TAIL LAMP LOWER PANEL (OUTER) SELANT <i>new</i>	2	\$ 80.00	\$ 160.00 <i>+</i>
10	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
11	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00 <i>60</i>
13	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
14	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00 <i>+</i>
15	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00 <i>200</i>
16	REVERSE CAMERA <i>new</i>	1	\$ 550.00	\$ 550.00 <i>+</i>

420

TOTAL \$ 2,140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
5	REAR CHASSIS ALIGNMENT	\$ 250.00	X
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
8	FOUR WHEEL ALIGNMENT	\$ 120.00	X
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	X

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SLE2911P
 MODEL : HONDA SHUTTLE
 DATE OF ACCIDENT : 26.02.2023
 TIME OF ACCIDENT : 15:50 HOURS

10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	X
----	--	-----------	---

1880

TOTAL \$ 5,860.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 13,362.64
 TOTAL LABOUR COST : \$ 5,860.00
 TOTAL REPAIR COST : \$ 19,222.64

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Admin Lj
 2/s 28/02/23.
 06 Days.

total: 7253.60.

4/s: 5.8K ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: