



16	Front grille	Bucl wrap	1		3,400.00	3,400.00	✓
17	Front grille hinge		1	DIJ	530.00	530.00	✓
18	Interior roof trim	Bucl/Return	1		8,700.00	8,700.00	✓
19	Wiper motor		1	Sm	2,980.00	2,980.00	✓
20	Front inner panel structure		1	Bj	4,200.00	4,200.00	✓
21	Sealant	Mm	10		40.00	400.00	✓
22	ERP	Mm	1		26.00	26.00	✓
23	Front grille chrome emblem		1	Red	330.00	330.00	✓
24	Labour to remove front lower windscreen		1		1,200.00	1,200.00	1000
25	Labour to remove front upper windscreen		1		1,000.00	1,000.00	600
26	Labour to remove roof trims, upholstery, seats etc to assist repair		1		600.00	600.00	400
27	Labour to remove & refit electronic dashboard		1		600.00	600.00	400
28	Labour to configure new electronic dashboard		1		300.00	300.00	✓
29	Check wiring for all affected electronics connections		1		500.00	500.00	400
30	Labour charges	@ 550/-	1		5,600.00	5,600.00	3850
31	Spray painting	(3 items)	1		2,800.00	2,800.00	1800
<b>SUB-TOTAL</b>						<b>S\$67,856.00</b>	

• Price before gst

Thank you  
Yours faithfully

*Winnie Char*

Winnie Char  
HP: 9850-9666



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/alter spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONNECT3

566 Woodlands Road (Mandal Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

REG: 53360061L

GST: 53360061L

QT23/PD778S/ODC

ALLIANZ INSURANCE COMPANY OF S'PORE PTE LTD
3 Temasek Avenue
609-01, Conferral Tower
Singapore 039190

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PD778S (Sup Items)

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Air ventilation control unit assy <i>Del</i>	1	2,100.00	2,100.00
2.	Interior panel glass <i>Shattered</i>	1	870.00	870.00
3.	Driver upper overhead casing <i>CM</i>	1	3,300.00	3,300.00
4.	Dashboard lower panel garnish <i>CM</i>	1	4,200.00	4,200.00
5.	Sealant <i>Mc</i>	1	40.00	40.00
6.	Labour to remove & refit interior panel glass	1	60.00	60.00
<b>SUB-TOTAL</b>				<b>S\$10,570.00</b>

115515

\* Price before gst

Thank you  
Yours faithfully,

Winnie Chai  
HP: 9850-9666



# PD 778D

4200.00	2100.00	1000.00	52276.00
2900.00	870.00	600.00	10570.00
720.00	3300.00	400.00	8750.00
340.00	4200.00	400.00	71596.00
4900.00	40.00	300.00	
2200.00	60.00	400.00	
4760.00	10570.00	3850.00	
2160.00		1800.00	
2700.00		8750.00	
900.00			
1170.00			
510.00			
230.00			
4100.00			
2900.00			
3400.00			
530.00			
8700.00			
4200.00			
400.00			
26.00			
330.00			
52276.00			