

Not Authorized  
 Purvey B4 paint  
 Ex 84500  
 12 days

**CONNECT 3**

566 Woodlands Road ( Mandai Estate ) Singapore 728697  
 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L  
 G S T : 5 3 3 6 0 0 6 1 L

QT23/PD778S/ODC

<b>ALLIANZ INSURANCE COMPANY OF S'PORE PTE LTD</b>
3 Temasek Avenue
#09-01 Centennial Tower
Singapore 039190

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PD778S

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front windscreen lower <i>CM</i>	1	4,200.00	4,200.00
2.	Front windscreen upper <i>CM</i>	1	2,900.00	2,900.00
3.	Front windscreen lower inner seal <i>me</i>	1	720.00	720.00
4.	Front windscreen upper inner seal <i>me</i>	1	340.00	340.00
5.	Front RH & LH headlamp assy <i>CM</i>	1	2,450.00	4,900.00
6.	Front RH & LH headlamp inner frame structure <i>CM</i>	1	1,100.00	2,200.00
7.	Front bumper RH & LH <i>CM</i>	1	2,380.00	4,760.00
8.	Front bumper inner structure RH & LH	1	1,080.00	2,160.00
9.	Front center bumper <i>CM</i>	1	2,700.00	2,700.00
10.	Front center bumper inner structure	1	900.00	900.00
11.	Front bumper RH, & LH bracket	1	585.00	1,170.00
12.	Front RH & LH wiper cover <i>CM</i>	2	255.00	510.00
13.	Front RH & LH wiper blade <i>CM</i>	2	115.00	230.00
14.	Front panel outer <i>CM</i>	1	4,100.00	4,100.00
15.	Front panel inner structure	1	2,900.00	2,900.00

Handwritten checkmarks and symbols on the right side of the table, including vertical lines and question marks, likely indicating item verification or status.

16	Front grille	<i>Buc / Nap</i>	1	3,400.00	3,400.00	✓
17	Front grille hinge		1	530.00	530.00	?
18	Interior roof trim	<i>Buc / Mc Lam</i>	1	8,700.00	8,700.00	✓
19	Wiper motor		1	2,980.00	2,980.00	?
20	Front inner panel structure		1	4,200.00	4,200.00	?
21	Sealant	<i>M</i>	10	40.00	400.00	✓
22	ERP	<i>M</i>	1	26.00	26.00	✓
23	Front grille chrome emblem		1	<i>Nil</i> 330.00	330.00	✓
24	Labour to remove front lower windscreen		1	1,200.00	1,200.00	1000
25	Labour to remove front upper windscreen		1	1,000.00	1,000.00	600
26	Labour to remove roof trims, upholstery, seats etc to assist repair		1	600.00	600.00	400
27	Labour to remove & refit electronic dashboard		1	600.00	600.00	400
28	Labour to configure new electronic dashboard		1	300.00	300.00	?
29	Check wiring for all affected electronics connections		1	500.00	500.00	400
30	Labour charges	<i>@ 550t</i>	1	5,600.00	5,600.00	3850t
31	Spray painting	<i>(3 items)</i>	1	2,800.00	2,800.00	1800
<b>SUB-TOTAL</b>					<b>SS67,856.00</b>	

- Price before gst

Thank you  
Yours faithfully

*Winnie*  
Winnie Chai  
HP: 9850-9666



**LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: