

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)176 Sin Ming Drive #04-06, Sin Ming Autocare
Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	SPMF1000000534	Date of Loss:	09/03/2023
Vehicle Reg. No.:	SML7608J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	BIZTEK LEASING	Contact No:	+6598321500
Driver:	LIM GUANG XIAN		
Make/Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Vehicle Reg. Date:	29/09/2014
Vehicle Colour:	Red		
Engine No:	P520227730	Chassis No:	JM6BM42A8F0143196
Odometer:	127387 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	14,184.50
Miscellaneous Items	535.00
Labour	2,860.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	17,579.50
+ GST 8.00% (S\$)	1,406.36
Nett Amount (S\$)	18,985.86

This claim is handled by: **HENRY LEE YOON SANG**Generated using *Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Mar 2023)

Parts: 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SML7608J/11/03/2023 12:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*560.00 F
2	1		*FRONT BUMPER RETAINER RH	0.00	0.00	*35.00 F
3	1		*FRONT BUMPER RETAINER LH	0.00	0.00	*35.00 F
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	*340.00 F
5	1		*FRONT BUMPER FOAM	0.00	0.00	*100.00 F
6	1		*FRONT BUMPER LOWER GARNISH	0.00	0.00	*135.00 F
7	1		*FRONT BUMPER UPPER SUPPORT MLDG	0.00	0.00	*140.00 F
8	1		*FRONT BUMPER SIDE TRIM COVER LH	0.00	0.00	*25.00 F
9	1		*BONNET	0.00	0.00	*720.00 F
10	1		*BONNET HINGE RH	0.00	0.00	*40.00 F
11	1		*BONNET HINGE LH	0.00	0.00	*40.00 F
12	1		*BONNET LOCK	0.00	0.00	*115.00 F
13	1		*BONNET INSULATOR	0.00	0.00	*165.00 F
14	1		*BONNET STAND	0.00	0.00	*65.00 F
15	1		*BONNET STAND HOOK	0.00	0.00	*15.00 F
16	1		*FRONT GRILLE BASE	0.00	0.00	*380.00 F
17	1		*FRONT GRILLE CHROME TRIM RH	0.00	0.00	*110.00 F
18	1		*FRONT GRILLE CHROME TRIM LH	0.00	0.00	*110.00 F
19	1		*FRONT LOWER GRILLE	0.00	0.00	*130.00 F
20	1		*FRONT GRILLE CTR BRACKET	0.00	0.00	*50.00 F
21	1		*FRONT GRILLE UPPER GARNISH	0.00	0.00	*280.00 F
22	1		*FRONT GRILLE BADGE	0.00	0.00	*35.00 F
23	1		*FRONT SUPPORT PANEL CPL	0.00	0.00	*360.00 F
24	1		*FRONT SUPPORT PANEL UPPER GARNISH	0.00	0.00	*125.00 F
25	1		*FRONT FENDER RH	0.00	0.00	*220.00 F
26	1		*FRONT FENDER LH	0.00	0.00	*220.00 F
27	1		*FRONT FENDER INNER COVER RH	0.00	0.00	*90.00 F
28	1		*FRONT FENDER INNER COVER LH	0.00	0.00	*90.00 F
29	1		*HEADLAMP ASSY RH	0.00	0.00	*1,550.00 F
30	1		*HEADLAMP ASSY LH	0.00	0.00	*1,550.00 F
31	1		*HEADLAMP BRACKET RH	0.00	0.00	*55.00 F
32	1		*HEADLAMP BRACKET LH	0.00	0.00	*55.00 F
33	1		*FOG LAMP COVER WITH CHROME TRIM RH	0.00	0.00	*75.00 F
34	1		*FOG LAMP COVER WITH CHROME TRIM LH	0.00	0.00	*75.00 F
35	1		*RADIATOR ASSY	0.00	0.00	*650.00 F
36	1		*RADIATOR AIR GUIDE RH	0.00	0.00	*80.00 F
37	1		*RADIATOR AIR GUIDE LH	0.00	0.00	*80.00 F
38	1		*RADIATOR UPPER BRACKET RH	0.00	0.00	*50.00 F
39	1		*RADIATOR UPPER BRACKET LH	0.00	0.00	*50.00 F
40	1		*CONDENSOR ASSY	0.00	0.00	*600.00 F
41	1		*A/C SUCTION HOSE	0.00	0.00	*185.00 F
42	1		*A/C DISCHARGE HOSE	0.00	0.00	*165.00 F
43	1		*FAN SHOURD ASSY CPL	0.00	0.00	*780.00 F
44	1		*WASHER TANK	0.00	0.00	*130.00 F
45	1		*WASHER TANK PUMP	0.00	0.00	*180.00 F
46	1		*AIR FILTER UPPER HOUSING	0.00	0.00	*135.00 F
47	1		*AIR FILTER LOWER HOUSING	0.00	0.00	*125.00 F

48	1	*AIR FILTER DUCT	0.00	0.00	*105.00 F
49	1	*AIR FILTER HOSE	0.00	0.00	*90.00 F
50	1	*HORN - HIGH PITCH	0.00	0.00	*120.00 F
51	1	*FRONT UPPER SEAL	0.00	0.00	*95.00 F
52	1	*ENGINE LOWER COVER	0.00	0.00	*185.00 F
53	1	*FRONT SHOCK ABSORBER RH	0.00	0.00	*280.00 F
54	1	*FRONT S/ABSORBER MOUNTING RH	0.00	0.00	*65.00 F
55	1	*FRONT KNUCKLE RH	0.00	0.00	*340.00 F
56	1	*FRONT LOWER ARM RH	0.00	0.00	*150.00 F
57	1	*LINKAGE RH	0.00	0.00	*90.00 F
58	1	*LINKAGE JOINT RH	0.00	0.00	*75.00 F

F=Franchise part.

Sub Total (S\$)	12,895.00
+ Margin on L,N Items 10.00% (S\$)	1,289.50

Total Parts (S\$)	14,184.50
--------------------------	------------------

Ding Auto Pte Ltd/SML7608J/11/03/2023 12:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRT CAR PLATE & FRAME	35.00
2	1	FRT GRILLE, BUMPER GARNISH, INNER COVER & PANEL - CLIPS	200.00
3	1	HEADLAMP - ECU RE-PROGRAMMING/RE-SETTING	300.00
Sub Total (S\$)			535.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	BODY REPAIR, PANEL BEAT & STRAIGHTEN/ALIGN - ACCIDENT AREA	New	1,200.00
2	SPRAY PAINT - FRONT BUMPER, BONNET, FRONT FENDER X2, GRILLE UPPER GARNISH & SUPPORT PANEL	New	1,200.00
3	REMOVE & REFIT - FRONT UNDERCARRIAGE COMPONENTS	New	300.00
4	REFILL - RADIATOR COOLANT	New	80.00
5	REFILL - AIR COND GAS	New	80.00
Gross Labour Cost (S\$)			2,860.00

Ding Auto Pte Ltd/SML7608J/11/03/2023 12:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >