

C

3570

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	8/13/23	D.O.I.	13/3/2023

Survey No. of Trip: _____	Survey Fee: _____
Site Insp (\$ _____)	Transportation _____
Interview (\$ _____)	\$ - RS. \$ _____
Tech Invs (\$ _____)	Fuels _____
Weekend (\$ _____)	Others _____
	TOTAL _____


Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721
 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: VOLKSWAGEN SCIROCCO
 Engine/Chassis No.: WVWZZZ13ZAV423221
 Date of accident: 08.03.23
 Damaged area: Rear

Date: 14/03/2023
 Claim Type: TP
 VRN: SJZ6191L

Not Authored
11 Days \$3550p
Recovery After Paint
4 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper upper <i>Buc/na</i>	1	\$ 1,159.20	\$ 1,159.20	
2	Rear bumper top carrier <i>230</i>	1	\$ 240.30	\$ 240.30	
3	Rear bumper side retainer <i>sm</i>	2	\$ 88.60	\$ 177.20	
4	Rear bumper licence plate lamp <i>cm 12</i>	1	\$ 105.10	\$ 105.10	
5	Tailgate	1	\$ 1,476.90	\$ 1,476.90	
6	Tailgate lock	1	\$ 215.00	\$ 215.00	
7	Tailgate lock striker	1	\$ 65.60	\$ 65.60	
8	Tailgate lock switch	1	\$ 279.70	\$ 279.70	
9	Tailgate lock immobilizer switch	1	\$ 235.60	\$ 235.60	
10	Tailgate "VW" logo c/w tailgate release	1	\$ 364.30	\$ 364.30	
11	Rear bumper side reflector <i>089</i> <i>115 m4cm 21</i>	2	\$ 135.80	\$ 271.60	
12	Tailgate inner trim board	1	\$ 483.20	\$ 483.20	
13	Tailgate weatherstrip	1	\$ 186.30	\$ 186.30	
14	Tailgate rubber stopper	2	\$ 36.60	\$ 73.20	
15	Tailgate hinge	2	\$ 87.20	\$ 174.40	
16	Tailgate damper	2	\$ 141.10	\$ 282.20	
17	Tailgate glass moulding	1	\$ 288.60	\$ 288.60	
18	Taillamp	2	\$ 798.20	\$ 1,596.40	
19	End panel	1	\$ 527.30	\$ 527.30	
20	End panel top garnish	1	\$ 198.60	\$ 198.60	
21	Rear bumper reinforcement <i>211</i>	1	\$ 563.90	\$ 563.90	
22	Rear bumper lower <i>395</i> <i>m4cm</i>	1	\$ 552.60	\$ 552.60	
23	Exhaust muffler	1	\$ 1,459.00	\$ 1,459.00	
24	Exhaust muffler holder	2	\$ 45.00	\$ 90.00	
25	Exhaust muffler heatshield	1	\$ 138.00	\$ 138.00	
Subtotal				\$ 11,309.30	
List discount				10.00%	
Total				\$ 10,178.37	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
2	Rear bumper clips	12	\$ 5.50	\$ 66.00
3	Reverse sensor	2	\$ 180.00	\$ 360.00
4	Tailgate inner trim board clips	10	\$ 5.50	\$ 55.00
5	Tailgate windscreen sealant	1	\$ 100.00	\$ 100.00
6	End panel sealant	1	\$ 120.00	\$ 120.00
7	End panel top garnish clips	6	\$ 5.50	\$ 33.00
8	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 839.00

435n
—
2005n
X
X
X
X
X

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To remove and replace exhaust assy.	0.5	\$ 100.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
6	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
7	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 2,700.00

4501
156
X
601
X
5501
X

Estimate Grand Total	\$ 13,717.37
----------------------	--------------