

REF: CTZ/230025991ky

Kenneth

SME 1974_{Yr} Regn: CR, 18

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A)

Make:

Colour

Sp.Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Sleering: In order / Jammed / Leaked / Burnt or

Brake: ~~loose~~ / Jammed / Leaked / Burnt or

Modl: NII / S/RIm / STD ~~A/RIm~~ or

Tyre Size: F:

R: 255/50R15

Front

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5-6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Des. of Damages : Frt / ~~Rear~~ / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass to?

☐: Prel. Report

59

☐: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$

☐ : Interview (S

☐ Tech Invs (\$

	Weekend (\$
1	100
2	100
3	100
4	100
5	100
6	100
7	100
8	100
9	100
10	100
11	100
12	100
13	100
14	100
15	100
16	100
17	100
18	100
19	100
20	100
21	100
22	100
23	100
24	100
25	100
26	100
27	100
28	100
29	100
30	100
31	100
32	100
33	100
34	100
35	100
36	100
37	100
38	100
39	100
40	100
41	100
42	100
43	100
44	100
45	100
46	100
47	100
48	100
49	100
50	100
51	100
52	100
53	100
54	100
55	100
56	100
57	100
58	100
59	100
60	100
61	100
62	100
63	100
64	100
65	100
66	100
67	100
68	100
69	100
70	100
71	100
72	100
73	100
74	100
75	100
76	100
77	100
78	100
79	100
80	100
81	100
82	100
83	100
84	100
85	100
86	100
87	100
88	100
89	100
90	100
91	100
92	100
93	100
94	100
95	100
96	100
97	100
98	100
99	100
100	100

Report Format :

Lump Sum / I.B.I: (\$

Date: 10/03/2023

Vehicle No: SME1974C

Model: MERCEDES BENZ GLC250 COUPE AMG

Chassis: WDC2533462F337032-2017

Reg.Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GT9168C

Date of Accident: 08/03/2023

Estimator:

TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		Re \$3,000.00 ✓
2	REAR BOOTLID "GLC 250" EMBLEM	1		Re \$120.00 ✓
3	REAR BOOTLID "4 MATIC" EMBLEM	1		Re \$100.00 ✓
4	REAR BOOTLID LAMP LH	1		Re \$580.00 X
5	REAR BOOTLID LAMP RH	1		Re \$580.00 X
6	REAR BOOTLID INNER LOCK	1		\$320.00 7
7	REAR BUMPER	1		Re \$1,100.00 ✓
8	REAR BUMPER REINFORCEMENT	1		\$850.00 7
9	REAR BUMPER SIDE RETAINER LH	1		Re \$180.00 X
10	REAR BUMPER SIDE RETAINER RH	1		Re \$180.00 A
11	REAR BUMPER INNER BRACKET	1		\$220.00 7
12	REAR BUMPER LOWER GARNISH	1		Re \$560.00 ✓
13	REAR BUMPER LOWER DIFFUSER	1		Re \$840.00 ✓
14	REAR BUMPER REFLECTOR LH	1		Re \$60.00 X
15	REAR BUMPER REFLECTOR RH	1		Re \$60.00 A
16	REAR EXHAUST CHROME TIP LH	1		Re \$460.00 X
17	REAR EXHAUST CHROME TIP RH	1		Re \$460.00 X
18	REAR END PANEL UPPER COVER	1		\$380.00 7
19	REAR END PANEL	1		REPAIR
SUB TOTAL				\$10,050.00
LESS 10%				-\$1,005.00
PARTS TOTAL				\$9,045.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Re \$50.00 ✓
2	REAR NUMBER PLATE & HOLDER	1		Re \$80.00 45m
3	REAR END PANEL UPPER COVER CLIPS	1		\$40.00 ?
4	WRAP FOR AFFECTED AREAS	1	(B.H.)	\$1,000.00 7
S/N TOTAL				\$1,170.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/03/2023
Vehicle No: SME1974C
Model: MERCEDES BENZ GLC250 COUPE AMG
Chassis: WDC2533462F337032-2017
Reg. Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GT9168C
Date of Accident: 08/03/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00	?
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.	\$700.00	450
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	?
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	20

LABOUR TOTAL \$2,040.00

TING AN

TOTAL \$12,255.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

8 Kung Chong Road Singapore 150143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

8A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9219 | Fax: (+65) 6481 1983

Branch (Motor Insurance Claims)

8B 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

