

Date: 10/03/2023

Vehicle No: SME1974C

Model: MERCEDES BENZ GLC250 COUPE AMG

Chassis: WDC2533462F337032-2017

Reg.Year: 2018

Third Party Insurer: CHINA TAIPING

Third Party Veh No: GT9168C

Date of Accident: 08/03/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID	1		Rs \$3,000.00 ✓
2	REAR BOOTLID "GLC 250" EMBLEM	1		Rs \$120.00 ✓
3	REAR BOOTLID "4 MATIC" EMBLEM	1		Rs \$100.00 ✓
4	REAR BOOTLID LAMP LH	1		Rs \$580.00 X
5	REAR BOOTLID LAMP RH	1		Rs \$580.00 X
6	REAR BOOTLID INNER LOCK	1		\$320.00 7
7	REAR BUMPER	1		Rs \$1,100.00 ✓
8	REAR BUMPER REINFORCEMENT	1		\$850.00 7
9	REAR BUMPER SIDE RETAINER LH	1		Rs \$180.00 X
10	REAR BUMPER SIDE RETAINER RH	1		Rs \$180.00 1
11	REAR BUMPER INNER BRACKET	1		\$220.00 7
12	REAR BUMPER LOWER GARNISH	1		Rs \$560.00 ✓
13	REAR BUMPER LOWER DIFFUSER	1		Rs \$840.00 ✓
14	REAR BUMPER REFLECTOR LH	1		Rs \$60.00 X
15	REAR BUMPER REFLECTOR RH	1		Rs \$60.00 1
16	REAR EXHAUST CHROME TIP LH	1		Rs \$460.00 X
17	REAR EXHAUST CHROME TIP RH	1		Rs \$460.00 X
18	REAR END PANEL UPPER COVER	1		\$380.00 7
19	REAR END PANEL	1		REPAIR
SUB TOTAL				\$10,050.00
LESS 10%				-\$1,005.00
PARTS TOTAL				\$9,045.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		Rs \$50.00 ✓
2	REAR NUMBER PLATE & HOLDER	1		Rs \$80.00 455n
3	REAR END PANEL UPPER COVER CLIPS	1		\$40.00 ?
4	WRAP FOR AFFECTED AREAS	1	(Bitt)	\$1,000.00 7
S/N TOTAL				\$1,170.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 10/03/2023
Vehicle No: SME1974C
Model: MERCEDES BENZ GLC250 COUPE AMG
Chassis: WDC2533462F337032-2017
Reg.Year: 2018

Third Party Insurer: CHINA TAIPING
Third Party Veh No: GT9168C
Date of Accident: 08/03/2023
Estimator: TING AN
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00	?
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOTLID, REAR BUMPER, REAR END PANEL & ETC.	\$700.00	450
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	\$150.00	120
LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOTLID INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	?
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$150.00	?
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$100.00	20
LABOUR TOTAL		\$2,040.00

TING AN

TOTAL**\$12,255.00****Head office**

6 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

