

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0245/2023/EQ
DATE : 6-Mar-23
WIP : 10184

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MUHAMMAD HAZWAN SYAKIR BIN SULAIMAN
ADDRESS : BLK 875B TAMPINES STREET 86
#14-113
SINGAPORE 522875
TELEPHONE : HP +65 84682344
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220123179
VEHICLE NO : **SNH 4871 T**
MODEL CODE : AUDI A4 2.0 TFSI S-TRONIC
MODEL YEAR : 31/10/2022
ENGINE NO : DEM 036425
CHASSIS NO : WAUZZZF43NA013772
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Feb-23
PLACE OF ACCIDENT : PARKING LOT BLK 875B TAMPINES ST 86

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNH 4871 T

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00 ✓	
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,400.00 X	
3	TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL AL PARTS REMOVED.	\$	4,200.00 500	
4	TO RESPRAY REAR BUMPER, REAR END PANELLING, RHS REAR FENDER AND SPARE WHEEL HOUSING.	\$	3,500.00 550	
5	TO RENEW RHS EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$	480.00 X	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 10,132.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 4871 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,642.00	de ✓
2	REAR BUMPER FIXING PARTS	1	\$ 184.00	X
3	REAR BUMPER SECURING STRIP	1	\$ 133.00	de ✓
4	REAR BUMPER SECURING STRIP	1	\$ 264.00	?
5	REAR BUMPER SPOILER	1	\$ 292.00	de ✓
6	REAR BUMPER BRACKET - RH	1	\$ 241.00	?
7	REAR BUMPER REFLECTOR - LH / RH	2	\$ 102.00	LH X RH ✓
8	REAR OUTER TAIL LIGHT - RH	1	\$ 1,200.00	out ✓
9	REAR OUTER TAIL LIGHT TRIM - RH	1	\$ 36.00	?
10	REAR INNER TAIL LIGHT - RH	1	\$ 1,200.00	X
11	REAR INNER TAIL LIGHT TRIM - RH	1	\$ 36.00	X
12	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,197.00	?
13	REAR BUMPER IMPACT BAR GASKET - LH / RH	2	\$ 34.00	?
14	REAR BUMPER GUIDE SECTION - RH UPPER	1	\$ 54.00	?
15	REAR BUMPER GUIDE SECTION - LH / RH LOWER	2	\$ 54.00	?
16	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 200.00	?
17	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	X
18	REAR PARKING AID SEAL RING	4	\$ 11.00	?
19	REAR BUMPER WIRING SET	1	\$ 452.00	X
20	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 491.00	X
SUB TOTAL SPARE PARTS		:	\$ 9,366.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNH 4871 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR TAILGATE OPENING SENSOR LINE	1	\$ 230.00	X
22	REAR AERIAL KEY ACCESS	1	\$ 123.00	X
23	REAR SILENCER - RH	1	\$ 1,700.00	X
24	REAR SILENCER DUAL CLIP	1	\$ 61.00	X
25	EXHAUST SILENCER BRACKET	1	\$ 48.00	X
26	EXHAUST TAIL PIPE TRIM - RH	1	\$ 406.00	NA ✓
27	REAR CROSS PANEL	1	\$ 290.00	X
28	REAR CROSS PANEL REINFORCEMENT	1	\$ 565.00	X
29	ACRYLIC SEALANT	S/N	\$ 180.00	X
30	CAVITY WAX	S/N	\$ 140.00	X
31	STONE CHIP	S/N	\$ 180.00	X
32	METAL FILLER POWDER	S/N	\$ 280.00	X
33	SUNDRIES		\$ 500.00	7
TOTAL SPARE PARTS		:	\$ 14,069.00	
TOTAL LABOUR CHARGES		:	\$ 10,132.00	
GRAND TOTAL		:	\$ 24,201.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanjin 97495749
Not Authorise

Ex: Hkn

14/3/23 21010

r/p Resurvey before paint 03 days
03 days
tanjin (Whanbun)

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT