



Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNJ2670J

ALLIANZ INSURANCE SINGAPORE PTE.  
LTD.  
MOTOR CLAIM DEPARTMENT  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897  
67143369

Vehicle & Document Information  
WIP No 63332  
Reg No/Reg Date SNJ2670J / 05/01/2023  
Date In/Mileage 10/03/2023/ 8387  
Chassis No W1N2477842J456542X  
Engine No 28291480930169  
Make/Model MB/GLA 180  
Colour/Trim 021 191 Cosmos Blac/ 041 101 Black

Account No	Terms	Date/Time Printed	CSE	Operator			
WA000001	Credit	13/03/2023/ 12:49	AQ	305 / Alan Quek Ai Lun			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

M BPNSUN POLICY NO/ACC DATE : AIS/2022/0005592 // 27-02-2023 DRIVE IN/EXCESS : 01-03-2023 // TBA DATE IN/DATE SURVEY: JASON // 10-03-2023 BY/AUTHORIZED ON :					
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10		380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT					120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.					960 1440.00
A BPIRES RESPRAY FRONT BUMPER			0.07		800 1080.00
X RH/F HEADLAMP	1.00	3361.30	00.00		3361.30
R FRT BUMPER	1.00	1171.52	00.00		1171.52
M FRT CROSS MEMBER	1.00	473.00	00.00		473.00
A FRT END SUPPORT MEMBER	1.00	728.80	00.00		728.80

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Alan Quek  
Cycle & Carriage Industries Pte Ltd  
Body Care & Repair Center  
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272  
Email: alan.quek@cyclecarriage.com.sg

Rgnl  
Hp 900100 GS  
3 days  
14/03/23 @ 1210  
EXCESS: TBA  
Revert  
Rgn before paint

Nett 8,674.62  
8% GST on 8674.62 693.97

Total Payable 9,368.59

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6298 1818