



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNJ2670J**Finalization**

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Rasul

Vehicle & Document Information

WIP No 63332
Reg No/Reg Date SNJ2670J / 05/01/2023
Date In/Mileage 10/03/2023/ 8387
Chassis No W1N2477842J456542X
Engine No 28291480930169
Make/Model MB/GLA 180
Colour/Trim 021 191 Cosmos Blac/ 041 101 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	16/03/2023/ 16:34		305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : AIS/2022/0005592 // 27-02-2023 DRIVE IN/EXCESS : 01-03-2023 // \$700 DATE IN/DATE SURVEY: 14-03-2023 // LKK RASUL BY/AUTHORIZED ON : LKK // 15-03-2023				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT				120.00
A BPILAB REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES RESPRAY FRONT BUMPER			0.05	800.00
X BPNEXC INSURANCE EXCESS				-700.00
X RH/F HEADLAMP	1.00	3361.30	00.00	3361.30
X FRT BUMPER	1.00	1171.52	00.00	1171.52
X FRT END SUPPORT MEMBER	1.00	728.80	00.00	728.80

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 6,821.62
8% GST on 6821.62 545.73

Authorized signatory and company stamp

Total Payable 7,367.35

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG