

CC3/AIG23002631/Tqp3

ASS. REP. = C.B.I. *Toupin*

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp. Est Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: ~~1000~~ 1000

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4270 K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: Tony

Vehicle: IN / OUT

Veh No: SNK 655L Yr Regn: 2023 Jan

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mini Q5 C.C. 1284Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 413 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: W44227FY4P201869Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NIL / S/Rim / STD A/Rim orTyre Size: F: 235/60R18R: 175BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/2/23 D.O.I. 14/3/23Survey held at Premium UbiDes. of Damages FR / Rear / O/S / N/S / U/C / Rooftop orOLS Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

04/08/23@3.21pm confirmed with Mr Boo final fig \$24273.08, 14 days. (Red \$15,387.92, 39%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: MER-ODLump Sum / E.B.I. 24273.08Days Of Repair: 14Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0238/2023/EQ  
**DATE** : 3-Mar-23  
**WIP** : 65490

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/2023**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
Attn: Motor Claims Dept  
**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MS ZHENG YANG  
**ADDRESS** : BLK 16 SHUNFU ROAD  
#06-55  
SINGAPORE 575749  
**TELEPHONE** : HP +65 97359885  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 7230008355  
**VEHICLE NO** : **SNK 655 L**  
**MODEL CODE** : AUDI Q5 2.0 TFSI QU S-TRONIC  
**MODEL YEAR** : 27/1/2023  
**ENGINE NO** : DMS 108173  
**CHASSIS NO** : WAUZZZFY4P2019869  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Feb-23  
**PLACE OF ACCIDENT** : OLEANER TOWER CAR PARK, LORONG 1 TOA PAYOH

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 655 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	✓
3	TO RENEW RHS 1/4 GLASS TO FACILIATATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	✓
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 4,660.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 655 L**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	3250
8	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 8,000.00	4175
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 19,252.00</b>	

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER / LOWER	1	\$ 3,600.00	Rp
2	REAR BUMPER GUIDE SECTION - RH	1	\$ 100.00	X
3	REAR BUMPER SIDE PANEL - RH	1	\$ 5,586.00	bt
4	REAR QUARTER WINDOW - RH	1	\$ 970.00	g pu to. res
5	WINDOW PRIMER	1	\$ 24.00	ne
6	REAR FUEL INSERT	1	\$ 183.00	X
7	REAR WHEEL HOUSING LINER - RH	1	\$ 326.00	X
8	REAR DOOR - RH	1	\$ 4,645.00	bt
9	REAR DOOR OUTER SEAL	1	\$ 242.00	res
10	BONDING AGENT	1	\$ 51.00	res
11	CLEANING SOLUTION	1	\$ 80.00	res
12	APPLICATOR	1	\$ 9.00	res
13	REAR DOOR SEALING STRIP	1	\$ 23.00	?
14	REAR DOOR ATTACHMENT PARTS	1	\$ 235.00	X
15	REAR DOOR CATCH	1	\$ 172.00	X
16	REAR DOOR SEAL BRACKET - RH	1	\$ 51.00	X
17	REAR SILL PANEL SEAL - RH	1	\$ 298.00	X
18	REAR DOOR COVER - RH	1	\$ 771.00	res plus fo
19	REAR DOOR HANDLE TRIM PLATE - RH	1	\$ 326.00	Rp
20	REAR DOOR HANDLE HOUSING - RH	1	\$ 23.00	X
<b>SUB TOTAL SPARE PARTS</b>		:	<b>\$ 17,715.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HANDLE COVER - RH	1	\$ 8.00	X
22	REAR WHEEL COVER - LH / RH	2	\$ 1,306.00	net ✓
23	ACRYLIC SEALANT	S/N	\$ 180.00	net ✓
24	CAVITY WAX	S/N	\$ 140.00	net ✓
25	STONE CHIP	S/N	\$ 180.00	net ✓
26	METAL FILLER POWDER	S/N	\$ 280.00	net ✓
27	1/4 GLASS SEALANT	S/N	\$ 100.00	net ✓
28	SUNDRIES		\$ 500.00	?
<b>TOTAL SPARE PARTS</b>		:	<b>\$ 20,409.00</b>	
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 19,252.00</b>	
<b>GRAND TOTAL</b>		:	<b>\$ 39,661.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Tanjin 97445749 / 62565561  
14/3/23 C1015 Not otherwise, Exit 109  
P/P Repair before paint  
Tanjin P/HK auto-won  
14 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD



JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT