

TOTAL

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0238/2023/EQ
DATE : 3-Mar-23
WIP : 65490

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 3/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ZHENG YANG
ADDRESS : BLK 16 SHUNFU ROAD
#06-55
SINGAPORE 575749
TELEPHONE : HP +65 97359885
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230008355
VEHICLE NO : **SNK 655 L**
MODEL CODE : AUDI Q5 2.0 TFSI QU S-TRONIC
MODEL YEAR : 27/1/2023
ENGINE NO : DMS 108173
CHASSIS NO : WAUZZZFY4P2019869
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10-Feb-23
PLACE OF ACCIDENT : OLEANER TOWER CAR PARK, LORONG 1 TOA PAYOH

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 655 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	✓
3	TO RENEW RHS 1/4 GLASS TO FACILIATATE RENEWAL OF RHS REAR FENDER.	S/N \$	300.00	✓
4	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,660.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 655 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	3250
8	TO RESPRAY REAR BUMPER, REAR LOWER BUMPER, RHS REAR FENDER, RHS REAR DOOR, DOOR HANDLE, RHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCE, ROOF CHANNEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 8,000.00	4175
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 19,252.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER - UPPER / LOWER	1	\$ 3,600.00	Rp
2	REAR BUMPER GUIDE SECTION - RH	1	\$ 100.00	X nn
3	REAR BUMPER SIDE PANEL - RH	1	\$ 5,586.00	bt 4468.80
4	REAR QUARTER WINDOW - RH	1	\$ 970.00	g pu to ner 775.60
5	WINDOW PRIMER	1	\$ 24.00	ne 18.80
6	REAR FUEL INSERT	1	\$ 183.00	X nn
7	REAR WHEEL HOUSING LINER - RH	1	\$ 326.00	X nn
8	REAR DOOR - RH	1	\$ 4,645.00	bt 3716.00
9	REAR DOOR OUTER SEAL	1	\$ 242.00	ner 193.20
10	BONDING AGENT	1	\$ 51.00	ner 40.80
11	CLEANING SOLUTION	1	\$ 80.00	ner 63.76
12	APPLICATOR	1	\$ 9.00	ner 6.96
13	REAR DOOR SEALING STRIP	1	\$ 23.00	? xnn
14	REAR DOOR ATTACHMENT PARTS	1	\$ 235.00	X nn
15	REAR DOOR CATCH	1	\$ 172.00	X bt ✓ 137.60
16	REAR DOOR SEAL BRACKET - RH	1	\$ 51.00	X nn
17	REAR SILL PANEL SEAL - RH	1	\$ 298.00	X nn
18	REAR DOOR COVER - RH	1	\$ 771.00	ner plus fo 616.40
19	REAR DOOR HANDLE TRIM PLATE - RH	1	\$ 326.00	Rp
20	REAR DOOR HANDLE HOUSING - RH	1	\$ 23.00	X nn
SUB TOTAL SPARE PARTS		:	\$ 17,715.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HANDLE COVER - RH	1 \$	8.00	X nn
22	REAR WHEEL COVER - LH / RH	2 \$	1,306.00	cut 1044.00
23	ACRYLIC SEALANT	S/N \$	180.00	net
24	CAVITY WAX	S/N \$	140.00	net
25	STONE CHIP	S/N \$	180.00	net
26	METAL FILLER POWDER	S/N \$	280.00	net
27	1/4 GLASS SEALANT	S/N \$	100.00	net
28	SUNDRIES	\$	500.00	? 34.16 nec ✓
TOTAL SPARE PARTS		:	\$ 20,409.00	
TOTAL LABOUR CHARGES		:	\$ 19,252.00	
GRAND TOTAL		:	\$ 39,661.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanjin 97445749 / 62565561
14/3/23 C1015 Not otherwise, Exit 109
P/P Repair before paint
Tanjin P/HK auto-won
14 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD



JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT