

Success United Pte Ltd (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	SU230062
Policy No:	SP2001652077	Date of Loss:	10/03/2023
Vehicle Reg. No.:	SMK7611D	Driveable?	
Driver Age/Info:	36 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	Lim Jing Jun	Contact No:	+6591451355
Driver:	Lim Jing Jun		
Make/Model:	HYUNDAI AD AVANTE, 1.6 GLS (A)	Vehicle Reg. Date:	24/04/2019
Vehicle Colour:	Blue		
Engine No:	G4FGKU112694	Chassis No:	KMHD841CMKU880765
Odometer:	48516 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	7,520.90
Miscellaneous Items	0.00
Labour	1,130.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	9,650.90
+ GST 8.00% (S\$)	772.07
Nett Amount (S\$)	10,422.97

This claim is handled by: **LAW YI TING**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2023)
 Parts: 143 HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Success United Pte Ltd/SMK7611D/13/03/2023 15:49
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Frt Bonnet	0.00	0.00	*680.00 F BUC
2	2		*Frt Bonnet Hinge L/R	0.00	0.00	*90.00 F BT
3	1		*Frt Bonnet Mechanism Lock	0.00	0.00	*80.00 F BT
4	1		*Frt Bonnet Lock Cable	0.00	0.00	*35.00 F XNN
5	2		*Frt Headlamp L/R L-CRA/OUT, R-CRA	0.00	0.00	*2,760.00 F
6	2		*Frt Headlamp Bracket L/R	0.00	0.00	*70.00 F
7	1		*Frt Bumper	0.00	0.00	*480.00 F CRA
8	1		*Frt Bumper Top Cover	0.00	0.00	*18.00 F CRA
9	1		*Frt Bumper Inner Top Bracket	0.00	0.00	*60.00 F ?
10	1		*Frt No.Plake Garnish	0.00	0.00	*28.00 F CRA
11	2		*Frt Bumper Side Holder L/R	0.00	0.00	*50.00 F ?
12	1		*Frt Bumper Inner Sponge	0.00	0.00	*75.00 F CRA
13	1		*Frt Bumper Reinforcement	0.00	0.00	*250.00 F BT
14	2		*Frt Bumper Lower Side Garnish Trim L/R	0.00	0.00	*130.00 F
15	1		*Frt Grille Assy	0.00	0.00	*480.00 F CRA
16	1		*Frt Bumper Weatherstrip	0.00	0.00	*25.00 F XNN
17	1		*Radiator Support Panel	0.00	0.00	*330.00 F ?
18	1		*Radiator Support Panel Top Garnish	0.00	0.00	*65.00 F XNN
19	1		*Horn	0.00	0.00	*58.00 F ?
20	1		*Radiator	0.00	0.00	*320.00 F ?
21	1		*Radiator Auxillary Fan Assy	0.00	0.00	*300.00 F ?
22	1		*Aircon Condenser	0.00	0.00	*300.00 F DD
23	1		*Air Intake Duct	0.00	0.00	*85.00 F ?
24	1		*Frt Bumper Clips	0	0.00	*30.00 FS NEC
25	1		*Frt No.Plake with Frame	0	0.00	*45.00 FS BT

F=Franchise part. S=SpcNett.

Sub Total (S\$)	6,844.00
+ Margin on L,N Items 10.00% (S\$)	676.90
Total Parts (S\$)	7,520.90

Success United Pte Ltd/SMK7611D/13/03/2023 15:49. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	To putty & respray painting on bonnet, bumper, frt fender LH, frt door LH.	New	800 1,000.00
Labour Items			
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	New	800.00 600
3	To remove, rearrange electrical wirings, check lighting.	New	30 80.00
4	To remove, replace aircon parts, vacuum refill gas & renew coolant.	New	150 250.00
Gross Labour Cost (S\$)			2,130.00

Success United Pte Ltd/SMK7611D/13/03/2023 15:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR 5 DAYS

- NOT AUTHORISE
- EXCESS \$0 (TBC)
- P/P OR I/S REPAIR
- SURVEY BY EDWARD TEL 62563561
- RESURVEY BEFORE PAINT FOR P/P REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: