

ALG

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0239/2023/EQ
DATE : 3-Mar-23
WIP : 65488

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/3/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ZHENG YANG
ADDRESS : BLK 16 SHUNFU ROAD
#06-55
SINGAPORE 575749
TELEPHONE : HP +65 97359885
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230008355
VEHICLE NO : **SNK 655 L**
MODEL CODE : AUDI Q5 2.0 TFSI QU S-TRONIC
MODEL YEAR : 27/1/2023
ENGINE NO : DMS 108173
CHASSIS NO : WAUZZZF4P2019869
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Feb-23
PLACE OF ACCIDENT : OLEANER TOWER CAR PARK LORONG 1 TOA PAYOH.SG

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNK 655 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00 1000	
4	TO RESPRAY FRONT BUMPER, LHS LOWER SPOILER, BONNET, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 4,000.00 1800	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,472.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,536.00	de ✓
2	FRONT BUMPER FIXING PARTS	1	\$ 269.00	X
3	FRONT BUMPER SECURING STRIP - LH	1	\$ 45.00	?
4	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 133.00	?
5	FRONT BUMPER UNDERRUN BAR - CENTER	1	\$ 1,027.00	X
6	FRONT BUMPER SPOILER - LH	1	\$ 266.00	int ✓
7	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 498.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 282.00	int ✓
9	FRONT PARKING AID SENSOR SUPPORT - LH	1	\$ 40.00	?
10	FRONT BUMPER TRIM - LH	1	\$ 190.00	?
11	FRONT BUMPER GUIDE SECTION - LH	1	\$ 46.00	?
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 210.00	X
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,104.00	X
14	FRONT BUMPER TOP COVER	1	\$ 152.00	X
15	CAUTION SIGN STICKER	1	\$ 17.00	X
16	AIR CONDITIONER STICKER	1	\$ 24.00	X
17	HORN LOW TONE - LH	1	\$ 220.00	X
18	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 543.00	X
19	FRONT PARKING AID SENSOR - LH	1	\$ 272.00	X
20	FRONT PARKING AID SEAL RING	4	\$ 11.00	X
SUB TOTAL SPARE PARTS		:	\$ 6,885.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNK 655 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRON BUMPER WIRING SET	1	\$ 457.00	X
22	FRONT FENDER - LH	1	\$ 1,607.00	bt -
23	FRONT FENDER BRACE - LH	1	\$ 266.00	?
24	FRONT FENDER BRACKET - LH	1	\$ 21.00	?
25	FRONT WHEEL HOUSING LINER - LH	1	\$ 309.00	X
26	FRONT WHEEL SPOILER - LH	1	\$ 191.00	X
27	FRONT FENDER CLOSURE PANEL - LH OUTER	1	\$ 37.00	X
28	FRONT FENDER PANEL COVER - LH	1	\$ 47.00	X
29	FRONT FENDER SHIELD - LH OUTER	1	\$ 93.00	X
30	HEADLIGHT MOUNTING - LH	1	\$ 140.00	?
31	HEADLIGHT - LH	1	\$ 7,887.00	eng -
32	LIFT CYLINDER - LH	1	\$ 162.00	X
33	LIFT CYLINDER HOSE	1	\$ 150.00	X
34	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 20.00	X
35	RADIATOR AIR GUIDE - LH	1	\$ 70.00	X
36	FRONT WHEEL COVER - LH / RH	2	\$ 1,504.00	ent -
37	SUNDRIES		\$ 400.00	?
TOTAL SPARE PARTS		:	\$ 20,246.00	
TOTAL LABOUR CHARGES		:	\$ 7,472.00	
GRAND TOTAL		:	\$ 27,718.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanji 7749 5749 / 62563561
14/3/23 @ 1025
Not to advise (Ex: fbg)
4 days
P/P Body before paint
tanji e/whatsapp

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT