5/30/23, 3:35 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI23002636/TQY3Q2

Date: 30/05/2023

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MAA00094

Claimant Vehicle Cupocator

No: SHD3217G Insured Vehicle No: SLF1642S

Date of Loss: 12/03/2023 Nature of Claim: TP Claim No: M2301642

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD3217G

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU296097

Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164468

Colour: Blue Odometer: 192922 km

Engine Capacity: 1580 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm
West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,431.68	1,271.92	159.76	11.16
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,580.00	960.00	620.00	39.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,022.68	2,242.92	779.76	25.80
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,022.68	1,800.00	1,222.68	40.45
+ GST 8.00/8.00% (S\$)	241.81	144.00	97.81	40.45
Nett Amount (S\$)	3,264.49	1,944.00	1,320.49	40.45

INSPECTION

Date of Assignment: 13/03/2023 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 14/03/2023 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 May 2023)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD3217G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	481.10 FL	*481.10 FL
2	1		*FRT BUMPER SIDE BRKT RH	Not Necessary	35.00 FL	*- FL
3	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*FRT FENDER RH	Bent	588.80 FL	*588.80 FL
5	1		*FRT FENDER SHIELD RH	Not Necessary	164.70 FL	*- FL
6	1		*FRT WHEEL CAP RH	Cut	346.40 FL	*346.40 FL
7	1		*FRT FENDER ADVERTISEMENT STICKER RH	Cut	100.00 F	*100.00 F
8	1		*FRT FENDER BLUE-DRIVE RH	Necessary	26.60 FL	*26.60 FL
F=Fra	nchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	1,764.60	1,564.90
			- List Item Discount on L	Items 20.00/20.00% (S\$)	332.92	292.98
				Total Parts (S\$)	1,431.68	1,271.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		11.00	11.00
	Sub Total (S\$)	11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	TUFF KOTE	New	60.00	30.00
4	WHEEL ALIGNMENT	New	120.00	80.00
		Gross Labour Cost (S\$)	1,580.00	960.00

Report was unsubmitted during this print-out. < END OF ESTIMATES >