Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd

> 20 McCallum Street #09-01 Tokio Marine Centre

Singapore 069046

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Telma Gomez Date: 22 May 2023

Preliminary Advice

Insured Vehicle No : SLF1642S

Attn:

TP Vehicle No : SHD3217G Accident Date : 12/03/2023 Make : HYUNDAI IONIQ HYBRID Assignment Date : 13/03/2023

Date of Inspection : 14/03/2023 Est. Duration of Repair

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

59 LOYANG DRIVE SINGAPORE 508969

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,022.68
Revised Amount	:S\$	2,242.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,242.92
Lump Sum Repair	:S\$	1,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

cle is uneconomical					

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject (X) to consistency check, part prices and labour cost.