

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22P00302400	Date of Loss:	03/03/2023
Vehicle Reg. No.:	SBN8829B	Driveable?	
Driver Age/Info:	41 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN JIAN ZHONG	Contact No:	+6590036705
Driver:	QUEK SIEW YEN FAITH		

Make/Model:	MERCEDES-BENZ C200 AMG LINE (R18 LED), 2.0 (A)	Vehicle Reg. Date:	22/12/2014
Vehicle Colour:	WHITE		
Engine No:	27492030206316	Chassis No:	WDD2050422F042080
Odometer:	5 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **4**

Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS

	Amount
Parts	3,921.50
Miscellaneous Items	0.00
Labour	1,580.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (S\$)	5,501.50
+ GST 8.00% (S\$)	440.12
Nett Amount (S\$)	5,941.62

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Mar 2023)
Parts: N/A MERCEDES-BENZ C200 AMG LINE (R18 LED) 2.0 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SBN8829B)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>de</i>	0.00	0.00	*800.00 F
2	1		*FRT BUMPER RETAINER RH <i>?</i>	0.00	0.00	*12.00 F
3	1		*FRT BUMPER INNER BRACKET RH <i>?</i>	0.00	0.00	*47.00 F
4	1		*FRT BUMPER UPPER CTR BRACKET <i>?</i>	0.00	0.00	*52.00 F
5	1		*FRT BUMPER SPONGE <i>?</i>	0.00	0.00	*80.00 F
6	10		*FRT BUMPER CLIP <i>m</i>	0.00	0.00	*50.00 F
7	1		*FRT GRILLE BASE <i>X</i>	0.00	0.00	*64.00 F
8	1		*FRT HEADLAMP RH <i>ca</i>	0.00	0.00	*2,370.00 F
9	1		*FRT HEADLAMP PANEL RH <i>X</i>	0.00	0.00	*90.00 F
F=Franchise part.						
Sub Total (S\$)						3,565.00
+ Margin on L,N Items 10.00% (S\$)						356.50
Total Parts (S\$)						3,921.50

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

		Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK FRT BOONET,FRT FENDER RH,WELD,REMOVE & FIX ON ABOVE PARTS	New 400 300	600.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New 600 400	700.00
3	TO CHECK WIRING	New	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New 100	250.00
Gross Labour Cost (\$)			1,580.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rene
Hp 90010568
4 days
4s
15/03/23 @ 1355
EXCER: TBA
Rever
Reg after
reper