

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG23002641/KYA3Q2**Date:** 20/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210055098		
Claimant Vehicle No :	SMB1408L	Insured Vehicle No :	SDR478M		
Date of Loss:	04/03/2023	Nature of Claim:	TP	Claim No:	4064792176SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB1408L	Engine No:	50334910493484
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Chassis No:	WMAA22ZZXD7001989
Reg. Date:	06/01/2014 (Man. Year: 2013)	Odometer:	704378 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 9 mm	Rear Left Side:	Firenza 9/9 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	Firenza 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,631.00	2,150.90	3,480.10	61.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,203.00	1,503.00	700.00	31.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,834.00	3,653.90	4,180.10	53.36
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	7,834.00	3,200.00	4,634.00	59.15
+ Loss of Use (4.0 x S\$250.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,202.00		

INSPECTION

Date of Assignment:	14/03/2023	Strides Automotive Services Pte Ltd (Woodlands)
Date Inspected:	14/03/2023 Inspected At:	60 Woodlands Industrial Park E4
Estimated Period of Repair:	3.0 days	Singapore 757705

Adjuster: KENNETH KONG**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP STOP :LED (MAN BUS)	Cracked	1,141.70 F	*1,141.70 FL
2	1		*COVER :REAR TAIL LAMP ,LH ,FOR MAN A22 BUS	Broken	974.70 F	*974.70 FL
3	1		*PANEL REFLECTOR REAR LH FOR MAN BUS	Cracked	107.00 F	*107.00 FL
4	1		*REFLECTOR TRIM FOR MAN BUS	Cracked	77.60 F	*77.60 FL
5	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
6	1		*STICKER 60KM/H	Necessary	5.00 FS	*5.00 FS
7	1		*BUMPER REAR CENTRE MAN A22 C SERIES	Repair	1,625.00 F	*- FL
8	1		*DOOR ENGINE REAR MAN A22 C SERIES	Repair	1,625.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,631.00	2,381.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	230.10
Total Parts (\$\$)	5,631.00	2,150.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,325.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	878.00	708.00
Gross Labour Cost (S\$)			2,203.00	1,503.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >