ASS. REC. BY: REF: A'G	123002641/kg
Kenneth	ASSIGNMENT
From: Date: Estimated Cost: OD VTP WS / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No:	Veh No: SMB 1408C Yr Regn: 01 14 Type: M.Car / M.Cycle (Bus Van / Lorry / Taxi / Prime Mover / Truck / Trailer or
at Workshop m/s PMRT	c.c / 03/A
of	2022 No. Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	The state of the s
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Institut Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: MID S/Rim / STD A/Rim or Tyre Size: F:
(Policy Condition)	
Permark: The veh had commenced its N/S	0/S RS/DIN/EXPONENCE 275/70R22.50
repair at the time of inspection.	O/S BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
Bal. or Market Value:	11016
IDAC Accident Rport: Consistent? : Yes or No	Eroni Rear Rear
GIA / PR Seen: Consistent?: Yes or No	mm R/Ba! 7 9 mm
Est. Repairs: 03 days Res.: Yes or No	mm L/Bal.
Lum Sum: 20 % 3 Val.: Yes or No	12123 000 1913 / 202
CA / REV / REP. / 24 HRS	Survey held at
Date: Person Contacted: Vehicle: IN / C	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
po-	7
29/3 6/kg & 32006 Certi	
1	
Re	
(4.)	
Oato/Timo, Filio Pass to?	
Prell. Report	Days Of Repair:
Oute/Time, File Return to?	Resurvey No. of T-1
2)	Transportation
Add Fe	e: : Site Insp (\$) _ s - Rs _ si
Roport Format	: Interview (\$
Report Format :	Tech Invs (\$) Others
Lump Sum / I.B.I: (S	Weekend (\$



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated: 14/03/2023

User ID : GohKK2

	Section A - Accident [Details
Registration Number	SMB1408L	
Case Reference Number	BUS/03/23/7002	
Registration Date	6/1/2014	
Company Type	SMRT Buses Ltd	
Make	MAN	
Model	MAN NL320F(A22)	
Name of Driver	Theenesh Kumar Narainan	
Type of Accident	Side Swipe	
Accident Date and Time	4/3/2023 10:33 PM	
Accident Reported Date and Time	8/3/2023 11:36 AM	
s Surveyor Required?	Yes	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number	1000	
Special Instruction to ARC,if any	SMB1408L - REAR LEFT PORTION SDR478M (TP) - INSURED WITH	ON I AIG
Prepared Date and Time	14/3/2023 8:00 AM	
Chassis Number	WMAA22ZZXD7001989	
Mileage		
Work Shop		
Repair Completion Date and Time		
LESS CONTRACTOR OF THE STATE OF	Section B - Summary of Rep	pair Estimates
Summary of Repair Estimates		
Culturally of Repair Desired	Quotation from ARC	Adjusted by Surveyor, if applicable
		00.00
Total Labour Cost	\$1,325.00	\$0.00
Total Spray Cost	\$878.00	\$0.00 \$0.00
Total Spare Part Cost	\$3,297.59	**************************************
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,500.59	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3days
Prepared / Adjusted By	ARC Manager Team	· ·
ARC / Surveyor Sign Off Date	14/03/2023 8:17 AM	
Signature	gi	*
Remarks		
The second secon		
	Section C - Quotation and Accid	ent Invoice Details
Quotation Number	Invoice	Number

Invoice Date

Prepared Date

Quotation Date

Invoice Amount



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685592 Estimator Telephone Number: 68662623 Accident Reporting Number : 68662672

Date Generated: 14/03/2023 User ID : GohKK2

Part 1 - Labour Works Adjusted by Surveyor, if applicable Job Scope Quotation from AR TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. \$1,325.00 795% Total Labour \$1,325.00 Part 2 - Spray Painting & Panel Beating Related Works Adjusted by Surveyor, if applicable Quotation from ARC Job Scope \$878.00 PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE 700% \$878.00 Total Spray Painting & Panel Beating Part 3 - Other Costs - Accident and Accident Repair Related Expense Quotation from ARC Adjusted by Surveyor, if applicable Total Other Costs Part 4 - Spare Parts / Material Usage List Price (\$) Discount (%) Final Price (\$) Estimator Approved Surveyor Approved Part Number Portion Stock Number | Part Name Quantity cm -6010298 LAMP,STOP:LED (MAN 1.00 \$1,141.70 10.00 \$1,027,53 Replace BUS) CMX nn \$1,146,69 6010299 SIGNAL LAMP LED \$1,274.10 Replace A COVER:REAR TAIL LAMP,LH,FOR MAN A22 \$877.23 F01001-CW271 \$974.70 Replace 6010060 1.00 Body Brow BUS PANEL, REFLECTOR: RE 10.00 \$107.00 \$96.30 1.00 Replace

Section D - Details of Repair Estimates

\$6,905.10 \$3,297.59 Total Added Spare Parts / Material Usage After Surveyor Signed off Stock Number | Part Name List Price \$ Discount (%) Final Price (\$) ARC Check Surveyor Check Part Number Portion Total

\$77.60

\$1,625.00

\$1,625.00

\$75.00

\$5.00

10.00

100.00

100.00

0.00

0.00

\$69.84

\$0.00

\$0.00

\$75.00

\$5.00

Replace

Repair

Repair

Replace

Replace

NOT Withains

con-

crs -

repair

× _{repair}

ne -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third parts survey is on a "Without Prejudice" basis
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

1 - Viedged by Repairer

6010372

6010371

6011408

6011407

Body

Body

Body

Body

4001F09-

ACCE5021

88-25215-0001

AR.LH.FOR MAN BUS

MAN BUS

REFLECTOR,TRIM:FOR

BUMPER:REAR.CENTR

DOOR,ENGINE:REAR,M AN A22 'C' SERIES

STICKER SMRT

STICKER 60KM/H

1.00

1.00

1.00

1.00

1.00