

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 14 Mar 2023

Preliminary Advice

Vehicle No	: SLT3273L	Accident Date	: 10/03/2023
Make	: HONDA CIVIC	Policy No.	: DMPCSNW00280642200
Assignment Date	: 14/03/2023	Excess	: S\$3,500.00
Date of Inspection	: 14/03/2023	Est. Duration of Repair	: 14 days
Inspection At	: DING AUTO PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,520.13
Revised Amount	:S\$	10,763.13
Check Items (Estimated)	:S\$	6,055.00
Total	:S\$	16,818.13
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	33,957.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,043.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.