

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKD5366K  
Accident Date : 04-Mar-2023

No. : 06779

Date : 07-Mar-2023

Our Ref : 023053 (AIG) / SHIJIE

PAGE : 1

LEK PUAY KOONG TINA  
52A TOH TUCK ROAD  
#09-04  
Singapore 596744

*NOT Authorised*  
*L1 Rep &*  
*Resurvey After Paint*  
*2-4 days*

## ESTIMATED COST OF REPAIR FOR TOYOTA CAMRY SKV7243Z

1 pc	Rear bumper	708.30	✓
1 pc	Rear bumper lower garnish	208.50	✓
1 pc	Rr bumper end panel undercover	445.00	✓
1 pc	Rear bumper reflector LH	65.00	X
1 pc	Rear bumper reflector RH	65.00	X
1 pc	Rear bumper side retainer LH	119.90	X
1 pc	Rear bumper side retainer RH	119.90	✓
1 pc	Rear bumper reinforcement	432.50	✓
1 pc	Rear end panel	727.70	✓
24 pcs	Reverse parking sensors	@ S\$373.60	1,494.40 ✓
		4,386.20	
		Less 25% :	1,096.55

1 pc Rear bumper clips

3,289.65  
30.00 sn ✓

To remove & refix reverse parking sensors

50.00 ✓

To remove, cut-out damaged parts, panel beating, welding, align,

600.00 ✓

To putty and spray replaced parts

800.00 ✓

Total : S\$ 4,769.65

Singapore Dollars Four Thousand Seven Hundred and Sixty Nine and Cents Sixty Five Only

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: