

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLT1757X (AIG)

Accident Date : 12-03-2023

Our Ref : SGN8686L / CHAN

HUI SHOON CAR RENTAL

C/O ALAN'S UNITED AUTO PTE LTD

Date : 14-03-2023

*NOT WITHIN  
Punery After Palm  
4 days*

## ESTIMATE COST OF REPAIR FOR TOYOTA ESTIMA SGN8686L

TO PANEL BEATING REAR RH DOOR , REAR RH FENDER , REMOVE F  
BUMPER FOR REPAIR ,ADJUST ,REFIX AND REALIGN REAR BUMPER

\$400.00 *300*

TO PUTTY AND SPRAY REAR RH DOOR , REAR RH FENDER , REAR BUMPER

\$700.00 *600*

TO REMOVE AND REPAIR REAR RH SPORT RIM AND REFIX

\$200.00 *100*

TO BALANCE AND COMPUTER WHEEL ALIGNMENT

\$65.00 *60*  
\$1,365.00

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Singapore Dollars One Thousand Three Hundred Sixty Five Only

Acknowledged by Repairer

Signature:

Date: