

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **HL Assurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MP319374	Date of Loss:	01/03/2023
Vehicle Reg. No.:	SLH3198J	Driveable?	
Driver Age/Info:	60 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAN GUEK LAI	Contact No:	+6597936267
Driver:	TAN GUEK LAI		
Make/Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Vehicle Reg. Date:	28/10/2016
Vehicle Colour:	GREY	Chassis No:	MRHDD4870GP000362
Engine No:	L15Z12874028		
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO SKETCH		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	2,323.60
Miscellaneous Items	0.00
Labour	2,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,853.60
+ GST 8.00% (S\$)	388.29
Nett Amount (S\$)	5,241.89

This claim is handled by: **SAMANTHA TAN YONG SING**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Mar 2023)
 Parts: M1-MPV HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SLH3198J/13/03/2023 13:46
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>SCA</i>	0.00	0.00	*160.00 F
2	1		*FRT BUMPER RETAINER RH	0.00	0.00	*8.00 F
3	1		*FRT BUMPER REINFORCEMENT <i>X</i>	0.00	0.00	*140.00 F
4	10		*FRT BUMPER CLIP <i>SCA</i>	0.00	0.00	*20.00 F
5	1		*FRT FOGLAMP RH	0.00	0.00	*140.00 F
6	1		*FRT FOGLAMP COVER RH <i>SCA</i>	0.00	0.00	*55.00 F
7	1		*FRT HEADLAMP RH <i>SCA</i>	0.00	0.00	*520.00 F
8	1		*REAR BUMPER <i>SCA</i>	0.00	0.00	*200.00 F
9	1		*REAR BUMPER RETAINER RH <i>EX</i>	0.00	0.00	*26.00 F
10	1		*REAR BUMPER SIDE ABSORBER RH	0.00	0.00	*34.00 F
11	1		*REAR BUMPER LWR CTR CHROME <i>CA</i>	0.00	0.00	*110.00 F
12	1		*REAR BUMPER LWR SIDE REFLECTOR RH <i>CA</i>	0.00	0.00	*15.00 F
13	10		*REAR BUMPER CLIP <i>SCA</i>	0.00	0.00	*20.00 F
14	1		*REAR BOOT LID <i>SCA</i>	0.00	0.00	*550.00 F
15	1		*REAR BOOT RS STICKER <i>SCA</i>	0.00	0.00	*18.00 F
16	1		*REAR BOOT MOBILIO STICKER <i>SCA</i>	0.00	0.00	*20.00 F
17	1		*REAR BOOT IVTEC STICKER <i>SCA</i>	0.00	0.00	*10.00 F
18	1		*REAR WINDSCREEN MOULDING <i>SCA</i>	0.00	0.00	*30.00 F
19	1		*REAR WINDSCREEN SEALANT <i>SCA</i>	0	0.00	*40.00 FS

F=Franchise part, S=SpcNett.

Sub Total (S\$)	2,116.00
+ Margin on L,N Items 10.00% (S\$)	207.60
Total Parts (S\$)	2,323.60

Sng Ah Tee Motor & Panel Service Pte Ltd/SLH3198J/13/03/2023 13:46. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	600 1,200.00
2	TO KNOCK FRT FENDER RH,RR FENDER RH,RR DOOR,WELD,REMOVE & FIX ON ABOVE PARTS	New	600 1,000.00
3	TO CHECK WIRING	New	30.00
4	TO REMOVE & REFIX REAR WINDSCREEN	New	120.00
5	TO DIAGNOSE & RESET FAULT CODE	New	80 180.00
Gross Labour Cost (S\$)			2,530.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SLH3198J/13/03/2023 13:46. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ramal
4p 90010068

6 days

43

17/03/23 P1430

EXCESS: 300

Revised

Resurvey after repair