



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23002659/Uqy3e2 Date: 12/04/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PD 5858Z	Veh. Inspected	GBK 3457P
	Policy No.	SD22V12877	Coverage (\$)	0.00
	Claim No.	BVS23/0211	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	14/03/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JTFAT35Y60K215115	Colour	WHITE
	Odometer	150574 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	TRIANGLE	6 mm
	L/H Front Tyre	195 R15	TRIANGLE	6 mm
	R/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
	L/H Rear Tyre	155 R12 (D)	FALKEN	6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/03/2023	Inspection Date	14/03/2023
	Survey held at	KAI MOTOR TRADING BLK 3007 UBI ROAD 1 #01-434 SINGAPORE 408701		
5a. Remarks				
	A)REGISTRATION DATE: 15 JUN 2020 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	