

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Apr 04 2023
	Ticket No: LKK-J000077	Vehicle No: SLP4961Z
	Policy No: 0	Claim No: 0
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Customer: Hock Chuan Hong Corporation Pte Ltd Vehicle: TOYOTA HARRIER 2 G 2016 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 67465519 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	REAR LH DOOR	Part	1.00	1,627.30	1,220.47	406.82	1,220.47	1,220.47
2	REAR LH DOOR LOWER MOULDING	Part	1.00	195.60	146.70	48.90	146.70	146.70
3	REAR LH FENDER MUD FLAG	Part	1.00	140.70	105.52	35.17	105.52	105.53
4	REAR LH SPORT RIM	Part	1.00	800.00	600.00	200.00	600.00	600.00
5	REAR LH ROCKER PANEL	Part	2.00	375.70	281.77	187.85	563.55	563.55
6	REAR LH ROCKER PANEL GARNISH	Part	1.00	645.10	483.83	161.28	483.83	483.83
							Taxable Value	3,120.07
							Discount Total	1,040.03
							Grand Total	3,120.08

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
7	REMOVE & REINSTALL DOOR GLASS	Labour	-	60.00	60.00	0.00	60.00	60.00
8	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	Labour	-	800.00	800.00	0.00	800.00	800.00
9	RESPRAY PAINTING	Labour	-	750.00	750.00	0.00	750.00	750.00
10	TUFF KOTE	Labour	-	50.00	50.00	0.00	50.00	50.00
							Taxable Value	1,660.00
							Discount Total	0.00
							Grand Total	1,660.00

		Parts Total	3,120.07
		Labour Total	1,660.00
		GST Total	0.00
		Grand Total	4,780.08
		Balance	4,780.08

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature