

Estimate

LKK AUTO CONSULTANTS PTE LTD Singapore, Singapore, Singapore, Singapore, Singapore - 575722. Contact: +65 62563561 Email: sur@lkkauto.com	Proforma Invoice No:	Date: Mar 14 2023
	TP Reg. No: SHB4891M	Insured Reg. No: SNB 1732M
	Ticket No: LKK-J000040	Accident Date: Mar 12 2023
Company Name: INDIA INTERNATIONAL INSURANCE Address: 64 Cecil Street,#04-02 IOB Building City: Singapore Region: Central Singapore Postal Code: 049711 Co.Reg.No: 198703792K	Engine No: G4LEJU111714	
	Policy No: 0	Claim No: 0
	Customer: Citycab Pte Ltd Vehicle: HYUNDAI IONIQ 1.6 DCT 2018 Kilometer: 0 Color: WHITE Fuel: PETROL PH: +65 98899184, +65 65508768 Email:	

#	Part Name	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Parts Total
1	REAR RH QUARTER PANEL	Part	1.00	1,768.30	1,060.98	707.32	1,060.98	1,060.98
2	REAR RH DOOR PANEL	Part	1.00	2,147.90	1,288.74	859.16	1,288.74	1,288.74
3	REAR RH WHEEL RIM COVER	Part	1.00	346.40	207.84	138.56	207.84	207.84
4	REAR RH DOOR FRAME FRONT BLACK TAPE	Part	1.00	7.00	4.20	2.80	4.20	4.20
5	REAR RH DOOR FRAME REAR BLACK TAPE	Part	1.00	7.00	4.20	2.80	4.20	4.20
6	REAR RH DOOR FRAME UPPER BLACK TAPE	Part	1.00	9.70	5.82	3.88	5.82	5.82
7	SET REAR BUMPER CLIP	Part	1.00	30.00	18.00	12.00	18.00	18.00
8	REAR QUARTER PANEL SEALANT	Part	1.00	40.00	24.00	16.00	24.00	24.00
9	REAR DOOR 'GOOGLE PLAY STORE' STICKER	Part	1.00	50.00	30.00	20.00	30.00	30.00
10	REAR DOOR ZIG STICKER	Part	1.00	60.00	36.00	24.00	36.00	36.00
11	REAR DOOR MOULDING CLIP	Part	1.00	30.00	18.00	12.00	18.00	18.00
12	REAR WINDSCREEN PRIMER	Part	1.00	40.00	24.00	16.00	24.00	24.00
13	REAR WINDSCREEN SEALANT	Part	1.00	40.00	24.00	16.00	24.00	24.00
							Taxable Value	2,745.78
							Discount Total	1,830.52
							Grand Total	2,745.78

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
14	TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	Labour	-	800.00	634.22	165.78	634.22	634.22
15	TO RUST PROOFING OF THE AFFECTED AREA	Labour	-	80.00	80.00	0.00	80.00	80.00
16	TO DIAGNOSTIC CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	Labour	-	100.00	100.00	0.00	100.00	100.00
17	TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	Labour	-	60.00	60.00	0.00	60.00	60.00
18	TO TRANSFER OF REAR DOOR MECHANISM TO NEW DOOR AND PERFORM WATER SEEPAGE TEST	Labour	-	60.00	60.00	0.00	60.00	60.00
19	TO REMOVE AND REFIT REAR TAILGATE UPPER AND LOWER WINDSCREEN TO ENABLE BODYWORK REPAIR	Labour	-	120.00	120.00	0.00	120.00	120.00
20	TO RESPRAY REAR BUMPER	Labour	-	200.00	200.00	0.00	200.00	200.00
21	TO RESPRAY REAR QUARTER PANEL	Labour	-	200.00	200.00	0.00	200.00	200.00
22	TO RESPRAY REAR DOOR PANEL	Labour	-	200.00	200.00	0.00	200.00	200.00
23	TO RESPRAY REAR DOOR PANEL OUTER HANDLE AND COVER	Labour	-	50.00	50.00	0.00	50.00	50.00

#	Service	Description	Quantity	Unit Price	Payable Amount	Discount	Taxable	Labour Total
24	TO RESPRAY REAR DOOR OUTER WAIST LINE MOULDING	Labour	-	50.00	50.00	0.00	50.00	50.00
25	TO RESPRAY SIDE SKIRT RH	Labour	-	100.00	100.00	0.00	100.00	100.00
							Taxable Value	1,854.22
							Discount Total	165.78
							Grand Total	1,854.22

					Parts Total	2,745.78
					Labour Total	1,854.22
					GST Total	0.00
					Grand Total	4,600.00
					Balance	4,600.00

I certify that the work has been done to my satisfaction and that I have taken delivery of the vehicle in good condition, with all items / valuables and parts intact.

Customer / Authorized Signatory

Service Advisor Signature

Cashier / Authorized Signature