

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 2453Z

| Qty | Description of Parts  | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS  |                         |                               |                   |
| 1   | FRONT L/H FENDER ASSY   | NOT NECESSARY           | 1,060.70                      | -                 |
| 1   | FRONT L/H FENDER HYBRID EMBLEM  | NOT NECESSARY           | 67.70                         | -                 |
| 1   | FRONT L/H DOOR ASSY   | DENTED                  | 1,435.20                      | 1,358.00          |
| 1   | FRONT L/H DOOR OUTER HANDLE   | NOT NECESSARY           | 423.20                        | -                 |
| 1   | FRONT L/H DOOR GLASS OUTER MOULDING   | DENTED                  | 108.70                        | 108.70            |
| 1   | FRONT L/H DOOR TOP BLACK STICKER  | NECESSARY               | 96.20                         | 96.20             |
| 1   | FRONT L/H DOOR WIND MIRROR  | DAMAGED                 | 1,399.60                      | 1,399.60          |
| 1   | FRONT L/H DOOR WIND MIRROR COVER  | TO REPAIR SEE<br>LABOUR | 142.30                        | -                 |
| 1   | REAR L/H DOOR BLACK STICKER   | NECESSARY               | 96.20                         | 96.20             |
| 1   | REAR L/H DOOR GLASS OUTER MOULDING  | NOT NECESSARY           | 108.70                        | -                 |
| 1   | REAR BUMPER ASSY  | NOT NECESSARY           | 677.60                        | -                 |
| 1   | L/H CENTRE OUTER LOWER STLL GARNISH   | NOT NECESSARY           | 688.70                        | -                 |
| 1   | REAR L/H DOOR ASSY  | DENTED                  | 1,401.70                      | 1,301.00          |
|     | LESS 25% DISCOUNT   |                         | -1,926.63                     | -1,089.93         |
|     |   |                         | 5,779.87                      | 3,269.77          |
|     | SPECIAL NETT ITEMS  |                         |                               |                   |
| 1   | REAR L/H SPORT RIM (SN)   | CUT                     | 450.00                        | 450.00            |
| 1   | REAR L/H TYRE (SN)  | NOT NECESSARY           | 180.00                        | -                 |
|     |   |                         | 630.00                        | 450.00            |
|     | <u>LABOUR</u>   |                         |                               |                   |
|     | TO SPRAY UNDERCOATING IN REPAIR.  |                         | 180.00                        | 50.00             |
|     | TO SEND VEHICLE FOR COMPUTER ALIGHTMENT.  |                         | 120.00                        | 80.00             |
|     | TO DISM / REWIRE DAMAGED PORTION.   |                         | 200.00                        | 30.00             |
|     | TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS. INCLUSIVE OF THE REPAIR OF FRONT L/H DOOR WIND MIRROR COVER. |                         | 1,000.00                      | 600.00            |
|     | TO PUTTY AND RESPRAY DAMAGED PORTION.   |                         | 1,200.00                      | 650.00            |
|     |   |                         | 2,700.00                      | 1,410.00          |
|     | GRAND TOTAL   |                         | 9,109.87                      | 5,129.77          |

Report Ref No. CS/SMO23002667/Awy3e2



Page No.:2 of 2

| RECOMMENDED COST OF LUMP SUM REPAIRS |  | 4,100.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION)      |  | ·        |

Report Ref No. CS/SMO23002667/Awy3e2



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.