



友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 10/04/2023 OUR REF: UAPL1591
REPAIR ESTIMATE TO YOUR TOYOTA PRIUS NO: SJW2453Z

- 1 FRONT L/H FENDER ASSY *new*
- 1 FRONT L/H FENDER HYBRID EMBLEM *new*
- 1 FRONT L/H DOOR ASSY *Dented*
- 1 FRONT L/H DOOR OUTER HANDLE *new*
- 1 FRONT L/H DOOR GLASS OUTER MOULDING *Dented*
- 1 FRONT L/H DOOR TOP BLACK STICKER *new*
- 1 FRONT L/H DOOR WIND MIRROR *new*
- 1 FRONT L/H DOOR WIND MIRROR COVER *new*
- 1 REAR L/H DOOR ASSY *Dented*
- 1 REAR L/H DOOR BLACK STICKER *new*
- 1 REAR L/H DOOR GLASS OUTER MOULDING *new*
- 1 REAR BUMPER ASSY *new*
- 1 L/H CENTRE OUTER LOWER STILL GARNISH *new*

LESS 25%.....

SPECIAL NETT:

- 1 REAR L/H SPORT RIM *ut*
- 1 REAR L/H TYRE *new*

LABOUR CHARGES:-

- TO SPRAY UNDERCOATING IN REPAIR
- TO SEND VEHICLE FOR COMPUTER ALIGNMENT
- TO DISM/REWIRE DAMAGED PORTION
- TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS.
- TO PUTTY AND RESPRAY DAMAGED PORTION

\$	1,060.70	X
\$	67.70	X
\$	1,435.20	1358
\$	423.20	X
\$	108.70	✓
\$	96.20	✓
\$	1,399.60	✓
\$	142.30	X
\$	1,401.70	1301
\$	96.20	✓
\$	108.70	X
\$	677.60	X
\$	688.70	X
\$	7,706.50	
\$	1,926.63	
\$	5,779.88	

\$	450.00	✓
\$	180.00	X

\$	180.00	50
\$	120.00	20
\$	200.00	30
\$	4,000.00	600
\$	1,200.00	600
\$	9,109.88	

total: 5129.77

L/s: 4.1K

05 Days

4.1K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: