

# Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716  
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg  
GST:201006949C RCB NO:201006949C

**M/S :** ALLIANZ INSURANCE SINGAPORE PTE LTD  
12 MARINA VIEW  
#14-01 ASIA SQUARE TOWER 2  
SINGAPORE 018961  
**TEL:** 63958963  
**ATTN:** Motor Claim Department \ ALLIANZ

**Estimate No:** EST1509446  
**Date:** 13 Mar 2023  
**Policy No:** P10313170R03  
**Veh Reg No:** SLW5727R  
**Make/Model:** MAZDA MAZDA6  
SEDAN 2.0 AT  
STANDARD EU6  
**Chassis No:** JM6GL1071J0135138  
**Engine No:** PE21019250  
**Reg. Date:** 22/02/2018


**Your Ref No:** TP 0323-7312  
**Claim Type:** Third Party  
**Accident Date:** 12/03/2023  
**TP Veh Reg No:** SNG8351G

## Estimate Repair Cost to Vehicle No :SLW5727R

Description	U/Price	Quantity	Price S\$	Amount S\$
<b>List Price</b>				
1 REAR BUMPER	1,266.000	1 PC	1,266.00	
2 REAR BUMPER SIDE HOLDER - LH/RH	41.0000	2 PC	82.00	
3 REAR BUMPER CLIPS	5.9000	10 PC	59.00	
4 REAR BUMPER REINFORCEMENT	523.0000	1 PC	523.00	
5 REAR BUMPER REFLECTOR - LH	53.0000	1 PC	53.00	
6 TAIL LAMP - LH	743.0000	1 PC	743.00	
7 REAR END PANEL	716.0000	1 PC	716.00	
8 REAR BUMPER SENSOR	268.0000	4 PC	1,072.00	
			4,514.00	
		Less 20%	902.80	3,611.20
<b>Labour</b>				
9 TO KNOCK OUT DENTS, REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	
10 TO RESPRAY PAINT ON ACCIDENT PORTIONS	800.0000	1 JOB	800.00	
11 TO CHECK WIRING	30.0000	1 JOB	30.00	
12 TO REMOVE, REFIT GARNISH	150.0000	1 JOB	150.00	
13 TO REMOVE, REPLACE REAR BUMPER SENSOR	100.0000	1 JOB	100.00	
			1,880.00	1,880.00
			Total	S\$ 5,491.20
			Add GST @ 8%	439.30
			Total Amount Payable	S\$ 5,930.50

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND NINE HUNDRED THIRTY AND CENTS FIFTY ONLY

For Progressive Car Care Pte Ltd

  
AUTHORISED SIGNATURE