



# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

*Jodie*  
21/03/23  
Tuesday

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
GST Reg No. 201629438M

14/03/2023

Owner: YOONG PUI MEI

*Not authorized*  
*Recovery B & paint*  
*4 days*  
*L1 Imp @ 3150/h*

**ESTIMATE TO REPAIR HONDA VEZEL - SNH4265T**

		<i>1203.50</i>			
1pc	rear tailgate			<i>Bdl/warp</i>	\$ 1,300.20 <i>✓</i>
1pc	rear tailgate outer garnish	<i>530.17</i>		<i>ndl/warp</i>	\$ 680.50 <i>✓</i>
1pc	rear tailgate "VEZEL" emblem			<i>na</i>	\$ 68.50 <i>—</i>
1pc	rear bumper	<i>1230.50</i>		<i>ndl/warp</i>	\$ 1,280.70 <i>✓</i>
1pc	rear bumper side retainer @\$38.00			<i>pr</i>	\$ 76.00 <i>✓</i>
1pc	rear bumper diffused			<i>ndl/wr</i>	\$ 458.20 <i>✓</i>
2pcs	rear bumper reflector @\$75.00			<i>pr</i>	\$ 150.00 <i>X</i>
1pc	rear bumper lower spoiler			<i>pr</i>	\$ 640.20 <i>X</i>
2pcs	rear bumper parking sensor @\$198.50			<i>pr</i>	\$ 397.00 <i>X</i>
2pcs	rear bumper parking sensor rubber @\$25.00			<i>pr</i>	\$ 50.00 <i>X</i>
1pc	rear windscreen moulding			<i>na</i>	\$ 198.00 <i>✓</i>

\$ 5,299.30  
\$ 1,059.86  
\$ 4,239.44

1set	rear number plate & casing			<i>CMA</i>	s.nett \$ 50.00 <i>455m</i>
	remove & refit rear windscreen glass				\$ 120.00 <i>✓</i>
	wiring				\$ 60.00 <i>15h</i>
	tuffkote				\$ 60.00 <i>30h</i>
	spray painting				\$ 800.00 <i>400h</i>
	labour charges				\$ 800.00 <i>400h</i>
	Total				\$ 6,129.44



**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_