

802.11ac

1000000

14/03/23

Tuesday

10/10

21/03/23

Tuesday

NOT Notified

Repairing B & painting

4 day

輝陽汽車有限公司

HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
 Tel: 64515752 (2 Lines) . Fax: 64514658
 GST Reg No. 201629438M

14/03/2023

Owner: YOONG PUI MEI

ESTIMATE TO REPAIR HONDA VEZEL - SNH4265T

1pc	rear tailgate		\$ 1,300.20	?
1pc	rear tailgate outer garnish	Net/wag	\$ 680.50	✓
1pc	rear tailgate "VEZEL" emblem	na	\$ 68.50	✓
1pc	rear bumper	Net/wag	\$ 1,280.70	✓
1pc	rear bumper side retainer @\$38.00	in	\$ 76.00	✓
1pc	rear bumper diffused	net/wag	\$ 458.20	✓
2pcs	rear bumper reflector @\$75.00	in	\$ 150.00	X
1pc	rear bumper lower spoiler		\$ 640.20	?
2pcs	rear bumper parking sensor @\$198.50		\$ 397.00	?
2pcs	rear bumper parking sensor rubber @\$25.00		\$ 50.00	?
1pc	rear windscreen moulding		\$ 198.00	?
			<hr/>	
			\$ 5,299.30	
	less 20%		\$ 1,059.86	
			<hr/>	
			\$ 4,239.44	
1 set	rear number plate & casing	CRM s.nett	\$ 50.00	455n
	remove & refit rear windscreen glass		\$ 120.00	?
	wiring		\$ 60.00	156
	tuffkote		\$ 60.00	?
	spray painting		\$ 800.00	400h
	labour charges		\$ 800.00	400d
	Total		<hr/>	
			\$ 6,129.44	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

