

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KUBER GLOBAL PTE LTD
 3 ANG MO KIO INDUSTRIAL PARK 2A #03-06
 AMK TECH I
 SINGAPORE 568050

*TP Budget Direct
 Xiao Chun.*

Contact : 91801356, 84279967

TAX INVOICE

Repair Code : CLM17672
 Date in : 14/03/2023
 Vehicle Num. : GBE5267P
 Model : FIAT DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
 Chassis/Eng# : ZFA26300006B18459/263A50007480851

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>Dented</i>	1	1480.00	✓ 1,480.00
FRONT RH DOOR INNER TRIM BOARD <i>could</i>	1	569.10	✓ 569.10
FRONT RH DOOR MECHANISM LOCK <i>Dented</i>	1	269.00	✓ 269.00
FRONT RH DOOR OUTER BLACK TAPE (HORIZONTAL) <i>3 New</i>	1	49.00	✓ 49.00
FRONT RH DOOR OUTER BLACK TAPE (VERTICAL)	1	48.00	✓ 48.00
FRONT RH DOOR OUTER GARNISH PROTECTOR <i>cut</i>	1	278.00	✓ 278.00
FRONT RH DOOR OUTER PULL HANDLE <i>New</i>	1	178.00	+ 178.00
FRONT RH DOOR WEATHER STRIP <i>Not in</i>	1	205.00	+ 205.00
FRONT RH DOOR WEATHER STRIP LOWER <i>New</i>	1	105.00	+ 105.00
REAR BUMPER <i>Dented</i>	1	1388.00	✓ 1,388.00
REAR BUMPER SIDE RETAINER L/R <i>RH Dented</i>	2	107.00	107 214.00
REAR RH CONTROL ARM <i>But</i>	1	368.00	✓ 368.00
REAR RH DOOR <i>Dented</i>	1	1680.30	✓ 1,680.30
REAR RH DOOR INNER TRIM BOARD <i>could</i>	1	469.00	✓ 469.00
REAR RH DOOR MECHANISM LOCK <i>Dented</i>	1	288.00	✓ 288.00
REAR RH DOOR OUTER BLACK TAPE (VERTICAL) <i>New</i>	1	48.00	✓ 48.00
REAR RH DOOR OUTER GARNISH PROTECTOR <i>cut</i>	1	288.00	✓ 288.00
REAR RH DOOR OUTER PULL HANDLE <i>Not in</i>	1	178.00	X 178.00

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KUBER GLOBAL PTE LTD
 3 ANG MO KIO INDUSTRIAL PARK 2A #03-06
AMK TECH I
 SINGAPORE 568050

Contact : 91801356, 84279967

TAX INVOICE

Repair Code : CLM17672
 Date in : 14/03/2023
 Vehicle Num. : GBE5267P
 Model : FIAT DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
 Chassis/Eng# : ZFA26300006B18459/263A50007480851

REAR RH DOOR ROLLER HINGE (BOTTOM) <i>new</i>	1	269.00	+ 269.00
REAR RH DOOR ROLLER HINGE (TOP) <i>new</i>	1	205.00	+ 205.00
REAR RH DOOR SLIDING RAIL <i>new</i>	1	498.00	+ 498.00
REAR RH DOOR SLIDING RAIL HINGE (CENTER) <i>new</i>	1	198.00	+ 198.00
REAR RH DOOR SLIDING RAIL OUTER COVER <i>new</i>	1	269.00	+ 269.00
REAR RH DOOR WEATHER STRIP <i>ht</i>	1	105.10	- 105.10
REAR RH FENDER <i>Dented</i>	1	2169.30	- 2,169.30
REAR RH FENDER INNER AIR VENT <i>new</i>	1	88.00	+ 88.00
REAR RH FENDER INNER SHIELD COVER <i>Dented</i>	1	158.00	✓ 158.00
REAR RH KNUCKLE ARM <i>Dented</i>	1	980.00	- 980.00
REAR RH LOWER ARM <i>Bent</i>	1	325.00	- 325.00
REAR RH RIM <i>Bent</i>	1	480.00	200(SAS) 480.00
REAR RH SHOCK ABSORBER <i>new</i>	1	305.00	+ 305.00
REAR RH TAILLAMP <i>new</i>	1	398.00	+ 398.00
REAR RH WHEEL HUB BEARING <i>and</i>	1	469.70	- 469.70
REAR RH WHEEL HUB COVER <i>ht</i>	1	263.60	- 263.60

11800.10
 10620.09
 S.N: 200

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KUBER GLOBAL PTE LTD
 3 ANG MO KIO INDUSTRIAL PARK 2A #03-06
 AMK TECH I
 SINGAPORE 568050

Contact : 91801356, 84279967

TAX INVOICE

Repair Code : CLM17672
 Date in : 14/03/2023
 Vehicle Num. : GBE5267P
 Model : FIAT DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
 Chassis/Eng# : ZFA26300006B18459/263A50007480851

			Subtotal before discount	15,283.10
	Percentage discount	10%		1,528.31
			Sub-total 1	13,754.79
FRONT RH DOOR COMPANY DETAIL STICKER	<i>New</i>	1	25.00	25.00 25.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	<i>New</i>	1	50.00	50.00 30
FRONT RH DOOR OUTER GARNISH CLIPS - SET	<i>New</i>	1	40.00	40.00 20
REAR BUMPER CLIPS - SET	<i>New</i>	1	80.00	80.00 30
REAR RH DOOR INNER TRIM BOARD CLIPS - SET	<i>New</i>	1	50.00	50.00 30
REAR RH DOOR OUTER GARNISH CLIPS - SET	<i>New</i>	1	50.00	50.00 20
REAR RH DOOR SLIDING RAIL OUTER COVER CLIPS - SET	<i>New</i>	1	50.00	50.00 50.00
REAR RH DOOR WINDOW GLASS MOULDING	<i>New</i>	1	80.00	80.00 30
REAR RH DOOR WINDOW GLASS SEALANT	<i>New</i>	1	80.00	80.00 30
REAR RH FENDER INNER SHIELD COVER CLIPS - SET	<i>New</i>	1	50.00	50.00 30
REAR RH FENDER INNER TRIM BOARD CLIPS - SET	<i>New</i>	1	40.00	40.00 30
REAR RH FENDER INNER TRIM CARPET	<i>New</i>	1	1000.00	1000.00 250
			Subtotal before discount	1,595.00
	Percentage discount	0%		0.00
			Sub-total 2	1,595.00
			Parts-total	15,349.79

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

KUBER GLOBAL PTE LTD
 3 ANG MO KIO INDUSTRIAL PARK 2A #03-06
 AMK TECH I
 SINGAPORE 568050

Contact : 91801356, 84279967

TAX INVOICE

Repair Code : CLM17672
 Date in : 14/03/2023
 Vehicle Num. : GBE5267P
 Model : FIAT DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
 Chassis/Eng# : ZFA26300006B18459/263A50007480851

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

50 ~~80.00~~

To remove, change window glass.

60 ~~150.00~~

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

200 ~~380.00~~

To road test driving, check and resetting wheel alignments system.

80 ~~120.00~~

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

60 ~~140.00~~

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

2590

80 ~~160.00~~

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

1000 ~~1,500.00~~

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1000 ~~1,600.00~~

To apply anti-rust chemical on repaired and replaced panel.

60 ~~120.00~~

Labour Total 4,250.00

Parts & Labour Total 19,599.79

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lj
 1/s 16/03/23.

09 Days

total: 13910.09
 1/s : 11.1K.