

Vehicle Damage Assessment Report for [SLZ6712K]

Estimate Created: 23/05/2023 14:58 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 23/05/2023 15:26 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	C-HR
Engine Type			
License Plate Number	SLZ6712K	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$7,000.00 WITH 6 WORKING
DAYS

Insurlogic 4 (23/05/2023 15:23)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear bumper		1	855.10	-25.00 %	641.33
Rear bumper side grille RH		1	187.00	-25.00 %	140.25
Rear bumper lower garnish		1	465.10	-25.00 %	348.83
Rear bumper reinforcement		1	352.70	-25.00 %	264.53
Rear bumper lower garnish reflector		1	145.40	-25.00 %	109.05
Reverse sensor		2	250.00	-25.00 %	375.00
Rear end panel		1	731.40	-25.00 %	548.55
Rear end panel top garnish		1	347.40	-25.00 %	260.55
Rear end panel antenna sensor		1	106.90	-25.00 %	80.18
Tailgate		1	1112.50	-25.00 %	834.38
Tailgate lock		1	389.40	-25.00 %	292.05
Tailgate lock cover		1	29.40	-25.00 %	22.05
Tailgate weatherstrip		1	371.40	-25.00 %	278.55
Tailgate inner pull pocket		1	38.40	-25.00 %	28.80
Tailgate outer garnish		1	882.20	-25.00 %	661.65
Tailgate inner trimboard		1	386.70	-25.00 %	290.03
Tailgate glass moulding		1	158.40	-25.00 %	118.80
Tailgate logo		1	72.20	-25.00 %	54.15
Tailgate CHR wording		1	55.60	-25.00 %	41.70
Tailgate Hybrid		1	121.40	-25.00 %	91.05
Spare tyre panel top cover		1	591.70	-25.00 %	443.78
Tools tray sponge		1	371.80	-25.00 %	278.85

Parts Subtotal 6,204.11

Materials

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
Rear bumper clips		1.0	30.00	0.00 %	30.00
Rear end panel top garnish clips		1.0	20.00	0.00 %	20.00
Rear end panel sealant		1.0	60.00	0.00 %	60.00
Tailgate outer garnish clips		1.0	30.00	0.00 %	30.00
Tailgate inner trim board clips		1.0	30.00	0.00 %	30.00
Tailgate glass sealant		1.0	60.00	0.00 %	60.00

Materials Subtotal 230.00

LaborReplace/RnR

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	800.00	0.00 %	800.00
Check wiring	RnR	30.00	0.00 %	30.00
To apply tuff coat	RnR	80.00	0.00 %	80.00
To remove upholstery	RnR	80.00	0.00 %	80.00
To transfer tailgate fittings	RnR	60.00	0.00 %	60.00
To remove and tailgate glass	RnR	120.00	0.00 %	120.00
To remove and reverse sensor	RnR	50.00	0.00 %	50.00
To remove rear camera	RnR	50.00	0.00 %	50.00
To remove rear video recorder.	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting	Full spray	1000.00	0.00 %	1,000.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 1,320.00

Paint Labor Subtotal 1,000.00

Labor Subtotal 2,320.00

Summary

Repair Cost 8,754.11

Discount(20 %) (1,754.82)

6,999.29

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal 6,999.29