

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TP Ego.
Hui Roy

Page No. 1

Vehicle No. SLZ6712K (2018)

TOYOTA CHR

ZYX102116774

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	REAR BUMPER <i>Delcd</i>		855.10	✓
2	REAR BUMPER SIDE HOLDER @112.20 <i>Me m</i>		224.40	X.
3	REAR BUMPER SIDE GRILLE @187.00 <i>RT torn</i>		374.00	187.
4	REAR BUMPER SIDE GRILLE REFLECTOR @59.00 <i>Me m</i>		118.00	X
5	REAR BUMPER TOW COVER <i>Me m</i>		27.70	X
6	REAR BUMPER LOWER GARNISH <i>Delcd</i>		465.10	✓
7	REAR BUMPER RINFORCEMENT <i>Best</i>		352.70	✓
8	REAR BUMPER UNDERCOVER @189.20 <i>Me m</i>		378.40	X.
9	REAR BUMPER LOWER GARNISH REFLECTOR <i>Delcd</i>		145.40	✓
10	REVERSE SENSOR @250.00 <i>Delcd</i>		500.00	✓
11	REAR END PANEL <i>Delcd</i>		731.40	✓
12	REAR END PANEL TOP GARNISH <i>Delcd</i>		347.40	✓
13	REAR END PANEL ANTENNA SENSOR <i>Delcd</i>		106.90	✓
14	TAILGATE <i>Delcd</i>		1112.50	✓
15	TAILGATE LOCK <i>Delcd</i>		389.40	✓
16	TAILGATE LOCK COVER <i>Delcd</i>		29.40	✓
17	TAILGATE LOCK STRIKER <i>Me m</i>		105.50	X.
18	TAILGATE WEATHERSTRIPE <i>lit</i>		371.40	✓
19	TAILGATE INNER PULL POCKET <i>Delcd</i>		38.40	✓
20	TAILGATE OUTER GARNISH <i>Delcd</i>		882.20	✓
21	TAILGATE INNER TRIM BOARD <i>Delcd</i>		386.70	✓
22	TAILGATE GLASS MOULDING <i>Me m</i>		158.40	✓
23	TOYOTA LOGO <i>2 per</i>		72.20	✓
24	CHR WORDING		55.60	✓
25	HYBRID EMBLEM		121.40	✓
26	REAR EXHAUST PIPE <i>2 per</i>		987.90	X
27	REAR EXHAUST PIPE MOUNTING <i>Me m</i>		45.00	X
28	REAR EXHAUST PIPE GASKET		45.40	X
29	REAR EXHAUST PIPE HEAT SHIELD <i>Delcd</i>		110.90	X
<i>Spec tyre Panel Top Coar. 591.70 ✓</i>			9538.80	
<i>Tools Tray Sponge 371.80 ✓</i>			2384.70	25%
			7154.10	
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS <i>Me m</i>		50.00	30
2	REAR END PANEL TOP GARNISH CLIPS <i>Me m</i>		20.00	✓
3	REAR END PANEL SEALANT <i>Me m</i>		60.00	✓
4	TAILGATE OUTER GARNISH CLIPS <i>Me m</i>		30.00	✓
5	TAILGATE INNER TRIM BOARD CLIPS <i>Me m</i>		30.00	✓
6	TAILGATE GLASS SEALANT <i>Delcd</i>		60.00	✓
Total Parts			250.00	

less

25%

25%

230

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

Page No. 2

Vehicle No. SLZ6712K

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	OUR ASSESSMENT (\$\$)
	<u>LABOUR</u>		
1	PANEL BEATING	1200.00 80	
2	SPRAY PAINTING	1200.00 100	
3	WIRING	50.00 30	
4	TO APPLY TUFF COAT	150.00 80	
5	TO REMOVE UPHOLSTERY	150.00 80	
6	TO TRANSFER TAILGATE FITTINGS	150.00 60	
7	TO REMOVE TAILGATE GLASS	180.00 120	
8	TO REMOVE REVERSE SENSOR	100.00 50	
9	TO REMOVE REAR CAMERA	100.00 50	
10	TO REMOVE REAR VIDEO RECORDER	100.00 50	
	Labour Total :	3380.00	2320
	TOTAL (PARTS & LABOUR):	10784.10	

total: 8754.07
L/s: 7K
06 Day >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7K