

Trans-cab Auto Services Pte Ltd
No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No Fax No. : 62571330
CO./ GST Reg. No. 201019626G
SHD5385R

AAD2303-

Not Authored
1/1/2023

08 MAR 2023

Vehicle No.:
Chassis No.:
Co UEN.:
Vehicle Make:
Vehicle Model:
Date of Accident:
Third Party Insurer:
Date of Registration:

SHD5385R
JTDKB3FU903078922
200303878K
TOYOTA
PRIUS
8/3/2023
SLJ7639S/ ALG-
11/1/2019

PART

LIST

- 1 COVER, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 SEAL, REAR BUMPER SIDE, LH
- 1 GUARD, REAR BUMPER, CENTER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 FILLER, REAR BUMPER EXTENSION, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, LH
- 1 COVER, REAR FLOOR
- 1 COVER, BACK DOOR TRIM
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PIPE ASSY, EXHAUST, TAIL
- 1 LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
- 1 LENS AND BODY, REAR LAMP, RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, LH (UPPER)
- 1 LENS AND BODY, REAR LAMP, LH
- 1 COVER, REAR COMBINATION LAMP, LH
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 STAY ASSY, BACK DOOR, LH
- 1 STAY ASSY, BACK DOOR, RH
- 1 HINGE ASSY, BACK DOOR, LH
- 1 HINGE ASSY, BACK DOOR, RH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1

\$	B ₁	558.39	✓
\$	B ₁	19.43	✓
\$	D ₁	148.58	✓
\$	M ₁	148.58	✓
\$	D ₁	111.41	✓
\$	D ₁	111.41	✓
\$	B ₁	726.92	✓
\$	B ₁	419.90	✓
\$		155.72	?
\$	M ₁ CM	155.72	✓
\$		220.50	?
\$		304.92	?
\$		290.43	?
\$	SM	31.50	X
\$		824.46	?
\$	R	2,086.98	X
\$		570.15	?
\$	CM	634.73	✓
\$	T ₁	81.48	X
\$		559.13	?
\$		634.73	?
\$	Red SM	81.48	✓
\$	B ₁	1,443.86	✓
\$	B ₁	305.66	X
\$	B ₁	305.66	X
\$	R	77.18	X
\$	R	77.18	X
\$	M ₁ CM	1,171.38	✓
\$	Red	68.88	✓
\$	Red	68.88	✓

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel Nc Fax No. : 62571330
 CO./ GST Reg. No. 201019626G
SHD5385R

AAD2303-

1 ORNAMENT SUB-ASSY, BACK DOOR

	\$	<i>na</i>	90.30	✓
TOTAL	\$		8,876.49	
25%	\$		2,219.12	
	\$		6,657.37	

SPECIAL NETT

1SET PARKING AID

- 1 REAR BUMPER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

	\$	<i>Ref</i>	700.00	<i>2201a</i>
	\$	<i>na</i>	65.00	<i>601a</i>
	\$	<i>na</i>	65.00	<i>601a</i>
	\$	<i>na</i>	65.00	<i>X</i>
	\$	<i>na</i>	60.00	<i>X</i>
	\$	<i>na</i>	100.00	<i>301a</i>
	\$	<i>na</i>	100.00	<i>301a</i>
	\$	<i>na</i>	180.00	<i>X</i>
	\$	<i>na</i>	150.00	<i>801a</i>
	\$	<i>na</i>	200.00	<i>—</i>
	\$	<i>na</i>	130.00	<i>301a</i>
TOTAL	\$		1,815.00	
TOTAL PARTS	\$		8,472.37	

LABOUR

To rust-proofing of the affected areas.

\$ 600.00 *7*

Putty and spray painting of the affected portion.

\$ 1,200.00 *801a*

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 *601*

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 *601*

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *601*

To reinstall rear bumper parking sensor.

\$ 170.00 *501*

To check steering geometry and computer wheel alignment

\$ *na* 220.00 *X*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD5385R

AAD2303-

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

	\$	<i>nan</i> 170.00	X
TOTAL	\$	<u>4,910.00</u>	

OVERALL TOTAL	\$	<u>13,382.37</u>
----------------------	----	------------------

5 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: