

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01  
Singapore 068897**Our File No:** CS6/AIS23002688/HVY3M4**Date:** 05/04/2023**REFERENCE**

Insured/Claimant:	ANG KIAN FOO	Policy No:	SP2003439553	
Date of Loss:	03/03/2023	Nature of Claim:	OD	Claim No: 202332005975

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKG3568S</b>		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ3020439
Reg. Date:	18/12/2007 (Man. Year: 2007)	Chassis No:	ZNE100392252
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:		Rear Tyre Size:	
Front Left Side:	5 mm	Rear Left Side:	5 mm
Front Right Side:	5 mm	Rear Right Side:	5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,287.00	1,287.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	1,020.00	560.00	35.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,867.00</b>	<b>2,307.00</b>	<b>560.00</b>	<b>19.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,600.00</b>		
<b>(S\$)</b>	2,867.00	1,600.00	1,267.00	44.19
<b>+ GST 8.00/8.00% (S\$)</b>	229.36	128.00	101.36	44.19
<b>Nett Amount (S\$)</b>	<b>3,096.36</b>	<b>1,728.00</b>	<b>1,368.36</b>	<b>44.19</b>

**INSPECTION**

Date of Assignment:	14/03/2023	Present Location:	SME Motor Pte Ltd (Kaki Bukit) SME MOTOR PTE LTD 1 KAKI BUKIT AVE 6 #02-15 (AUTOBAY @KAKI BUKIT) SINGAPORE 417883
Date Inspected:	14/03/2023	Inspected At:	
Estimated Period of Repair:	4.0 days		

**Adjuster:** Edward**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Apr 2023)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG3568S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR (WCP)	Dented	580.00 F	*580.00 F
2	1		*REAR LH DOOR (WCP)	Dented	590.00 F	*590.00 F
F=Franchise part.						
Sub Total (S\$)					1,170.00	1,170.00
+ Margin on L,N Items 10.00/10.00% (S\$)					117.00	117.00
Total Parts (S\$)					1,287.00	1,287.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRE CHECKING	New	30.00	0.00
2	TRANSFER 2 DOORS COMPONENTS FROM OLD TO NEW	New	250.00	120.00
3	LABOUR CHARGE	New	600.00	400.00
4	SPRAY PAINTING	New	700.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,580.00</b>	<b>1,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >