



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22011587/Tvy3e2-1 Date: 17/03/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBH 6783T	Veh. Inspected	SKZ 7360Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	22/22/22/VC06/026565	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	14/03/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA WISH	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JTDGG20W80J003460	Colour	GREY
	Odometer	205887 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	RXMOTION	6 mm
	L/H Front Tyre	185/60 R15	RXMOTION	6 mm
	R/H Rear Tyre	185/60 R15	RXMOTION	6 mm
	L/H Rear Tyre	185/60 R15	RXMOTION	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	22/10/2022	Inspection Date	21/11/2022
	Survey held at	ASTUTE AUTOWORKS PTE LTD 60 JALAN LAM HUAT, #02-16/17, CARROS CENTRE SINGAPORE 737869		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	