



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0041222

Date of Report : 30/12/2022

To : Mr Teo Boon Lian

C/o. Blk 9002 Tampines Street 93

#01-36

Singapore 528836

Date of Assignment : 05/12/2022

Report requested by : Mr Teo Boon Lian

Date of Accident : 01/12/2022

Date of Inspection : 05/12/2022

Claim No. : Third Party Claim

Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : **SNB7678Y**

Make & Model : Toyota Camry (Hybrid)

Date of Registration : 14/09/2021

Colour : Met. Grey

Engine Capacity (cc) : 2487

Mileage (km) : 8983km

Chassis / Frame No. : JTNB23HK503105069

Engine No. : A25A5644171

TYRE CONDITION

Front LH : 7 mm

Make : Bridgestone

Front RH : 7 mm

Make : Bridgestone

Rear LH : 7 mm

Make : Bridgestone

Rear RH : 7 mm

Make : Bridgestone

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good

Paintwork : Good

Handbrake : Serviceable

Footbrake : Serviceable

Steering : Serviceable

Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Tampines Auto Services

Blk 9002, Tampines Street 93, #01-36, Singapore 528836

ASSESSMENT

Repairer's Estimate : \$ 6,869.70

Revised Amount : \$ 4,894.00

Less Excess : \$ -

Recommended Reserve : \$ 3,920.00 (Lump Sum)

Estimated Normal Period of Repairs : ~~6~~ 5 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressee (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SNB7678Y

Report No. : PAS/TP/0041222

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Tampines Auto Services, Blk 9002, Tampines Street 93, #01-36, Singapore 528836.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the rear LH portion.

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, LH taillamp, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$4,894.00.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$3,920.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg: 201404434D

Vehicle No : SNB7678Y

Report No. : PAS/TP/0041222

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Boot lid	Dented/Repair	\$ 1,316.10	\$ -
2	1 pc	Boot lid emblem (Logo)	Necessary	\$ 85.20/	\$ 85.20/ <i>NEC</i>
3	1 pc	Boot lid emblem (Camry)	Necessary	\$ 85.90/	\$ 85.90/ <i>NEC</i>
4	1 pc	Boot lid emblem (Hybrid)	Necessary	\$ 65.10/	\$ 65.10/ <i>NEC</i>
5	1 pc	Boot lid reflector LH	Refit	\$ 429.50	\$ -
6	1 pc	Taillamp LH	Cracked	\$ 861.50/	\$ 861.50/ <i>CRA</i>
7	1 pc	Taillamp panel LH	Dented/Repair	\$ 226.10	\$ -
8	1 pc	Rr end panel	Dented/Distorted	\$ 777.80	\$ 777.80/ <i>DIS</i>
9	1 pc	Rr bumper	Dented	\$ 779.10/	\$ 779.10/ <i>BUC</i>
10	2 pcs	Rr bumper side grille R/L	LH Cracked	\$ 71.80/	\$ 35.90/ <i>CUT</i>
11	1 pc	Rr bumper ultrasonic sensor LH	Dented/Damaged	\$ 437.00/	\$ 437.00/ <i>SC</i>
12	1 pc	Rr bumper reflector LH	Cracked	\$ 71.40/	\$ 71.40/ <i>CRA</i>
13	6 pcs	Rr bumper clip	Necessary	\$ 21.60/	\$ 21.60/ <i>NEC</i>
14	2 pcs	Rr bumper retainer R/L	Necessary	\$ 175.40	\$ 175.40/ <i>NEC</i>
15	2 pcs	Rr bumper side bracket R/L	Cracked/Necessary	\$ 137.40	\$ 137.40/ <i>NEC</i>
16	1 pc	Rr bumper sponge	Dented/Cracked	\$ 106.50	\$ 106.50/
17	1 pc	Rr bumper reinforcement	Dented	\$ 512.20	\$ 512.20/ <i>DD</i>
18	1 pc	Boot lid	Dented/Repair		(Refer labour no. 4 & 5) <i>Rpt.</i>
19	1 pc	Rr fender LH	Dented/Repair		(Refer labour no. 2, 4 & 5)
20	1 pc	Rr floor panel	Dented/Repair		(Refer labour no. 2, 4 & 5)
21	1 pc	Rr chassis member LH	Dented/Repair		(Refer labour no. 2, 4 & 5)
				\$ 6,159.60	\$ 4,152.00
Less Discount : 25%				\$ 1,539.90	25% \$ 1,038.00
List Parts Sub-Total :				\$ 4,619.70	\$ 3,114.00
Parts Total :				\$ 4,619.70	\$ 3,114.00



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg 201404434D

Vehicle No : SNB7678Y

Report No. : PAS/TP/0041222

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	\$ 50.00	\$ 30.00
2	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 80.00	\$ 60.00
3	To remove, replace and/or transfer rear reverse sensors to new bumper. (Include reset/reprogram control unit)	\$ 120.00	\$ 120.00 ⁵⁰
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 770.00 ⁶⁰⁰
5	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 800.00 ⁶⁰⁰
Labour Total :		\$ 2,250.00	\$ 1,780.00
Total (Parts & Labour) :		\$ 6,869.70	\$ 4,894.00

REPAIR 5 DAYS

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 3,920.00

Under normal circumstances, the repairs should be completed within a reasonable period of ⁵ Working Days. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

46 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.