



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III23000377/Twy3e2-1	
			Date: 23/03/2023	
			Code: III2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLH 3063P	Veh. Inspected	EW 3993J	
Policy No.	D21MFL0000447_02	Coverage (\$)	0.00	
Claim No.	MFL2023D0000654	Excess (\$)	0.00	
Assign From	CARINE KEK	Assign Date	14/03/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ESTIMA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	ACR500075012	Colour	WHITE	
Odometer	265105 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	215/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	215/55 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	06/01/2023	Inspection Date	11/01/2023	
Survey held at	TOH PAINTING & SERVICES PTE LTD BLK C3, WOODLANDS ROAD #391-C & G YEW TEE INDUSTRIAL ESTATE SINGAPORE 677966			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	