

FBT 96610

CB 200X

金国摩托私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Towing — \$ 35 ~~for 1st~~

Towing to idec — \$ 35

40 s/n *

Fork repair — \$155 4/5 - 80 (CL) - Labour

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handle Bar — \$245 3/4 - 10% = 220.50

Mirror — \$ 98 scr / 10% - 88.20

Handle Balancer — \$68 scr - 10% - 61.20

Complete Signal light Right — \$138 scr ^{10%} / 124.20

Price

HP 900/0068

3 days

HP P/P

15/03/23 @ 15.20

Reey after
repair

P - 1545.30

s/n - 68.00

L - 330.00

T - 1943.30

3 days

Front Mudguard — \$ 120 ^{scr} repair 50 (CL) - Labour

Front Sport Rim — \$295 repair - 90 (CL) X 12

Front No. Plate — \$28 1/2 s/n *

Tank Side Cover — \$ 285 scr - 10% - 256.50
Right Side

Hand light Side cover Right — \$145 ^{10%} scr - 130.50

Fuel Tank Side Cover Right — \$285 scr ^{10%} / 256.50

Complete Engine ^{guard} Cap — \$190 - scr - 10% - 171.00

Right Rear Side Cover — \$98 scr ^{10%} - 88.20

Rear Mudguard — \$165 cr - 10% - 148.50

Labour — \$ 200 200 Labour

Total : \$2665.00