



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS/FCI23002692/Rny3e2 Date: 13/04/2023 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 8274J	Veh. Inspected	FBT 9661D
Policy No.		Coverage (\$)	0.00
Claim No.	D23000886MFCV	Excess (\$)	0.00
Assign From	CAROLINE CABRERA	Assign Date	14/03/2023
2. Vehicle Particulars & Condition			
Make & Model	HONDA CB200X ABS M	c.c	184
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	ME4MC564CNA002598	Colour	BLACK
Odometer	13431 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	110/70-17	MRF	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-17	MRF	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/03/2023	Inspection Date	15/03/2023
Survey held at	KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	