

SLK 5878B

- New bumper dec ✓ \$545
- New bumper clips dec ✓ \$30 SN
- Reverse sensor nw ✓ \$200 SN
- Tailgate bt ✓ \$1099.20
- Tailgate glass moulding - dec ✓ \$121.20
- Tailgate emblem Honda' dec ✓ \$70
- Tailgate emblem 'Vezel' dec ✓ \$58.60
- Tailgate weatherstrip twi ✓ \$198.60
- New smart keyless buzzer aw ✓ \$87
- New end panel RX \$517.30

2179.10

20% - 1743.28

SN \$230

Labor

- To Repair rear portion - \$500
- To Spray rear portion - \$600
- Wiring - \$30
- Tuff coat - \$30
- To remove / Refix reverse sensor - \$30.
- To Remove / Refix tailgate glass - \$120
- To Remove / Refix Tailgate mechanism \$60.

1370

1743.28

230

1370

3343.28

1/5 \$2650

4 days
\$

Range - \$3000 - \$4000