

(08/18/13) wef

ASS. REC. BY: Roma

REF:

CL4/MS23002696/R 393

9830

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJL 616Sat Workshop m/s WAT HONGof TOT GUAN RO EAST

Insured:

MS

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

110K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJL 616SYr Regn: 2018 / DECType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES BENZ CLA180B.LA c.c. 1555

Colour

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

59628

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 173422N674081Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

04/03/23

D.O.I.

20/03/23

Survey held at

WAT HONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 69K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJL616S MERCEDES BENZ CLA 1.6

Page No. 1

QTY	DESCRIPTION	RECOMMENDATION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR'S ADJUSTMENT		
<u>PARTS (LIST ITEMS)</u>							
1	Rear bumper <i>tor</i> ✓			906			
1	Rear bumper lower garnish <i>cm</i> ✓			264			
2	Rear bumper side retainer LH/RH@2*\$18 <i>LHX/RH-?</i>			36			
1	Tail lamp RH <i>bn</i> ✓			516			
1	Boot lid <i>repair</i> ✓			1140			
1	Boot lid lock <i>x</i>			138			
2	Boot lid hinges LH/RH @2*\$84 <i>x</i>			168			
1	Boot lid Emblem 'CLA180' <i>new</i> ✓			60			
1	Boot lid logo badge <i>new</i> ✓			60			
1	Rear towing cover <i>sc</i> ✓			42.00			
1	Exhaust cover chrome RH <i>scd</i> ✓			192.00			
1	Rear reverse Sensor RH/LH @2*\$118 <i>new</i> ✓			236.00			
1	Rear fender Shield RH <i>?</i>			90.00			
1	Rear Fender RH (Repair refer to labor)			0.00			
1	Rear Fender LH (Repair refer to labor)			0.00			
			Part Items Total:				
				10%	3848.00		
					384.80		
				4232.80			
<u>SPECIAL NETT ITEMS</u>							
1	Rear bumper clips <i>new</i> ✓			35.00			
1	Rear fender shield clips <i>?</i>			25.00			
SN Items Total:				60.00			
Total Parts				4292.80			



Wah Hona Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SJL616S MERCEDES BENZ CLA 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	600
3	To remove and replace rear reverse sensor	100.00	60
4	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	60.00	40
5	To remove and replace exhaust pipe cover	100.00	50
Labour Total :		2260.00	
TOTAL (PARTS & LABOUR):		6552.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Done
Hp 90010068
5 days
7/P
20/03/23 @ 1500
Resy after repair

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	983D
Vehicle Details	
Vehicle No.:	SJL616S
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Mar 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CLA180 AMG LINE AUTO
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	27091031656719
Chassis No.:	WDD1173422N674081
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,733.00
Original Registration Date:	14 Dec 2018
First Registration Date:	14 Dec 2018
Transfer Count:	0
Actual ARF Paid:	\$36,427.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Dec 2028
PARF Rebate Amount:	\$27,320.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$23,568.00
COE Rebate Amount:	\$13,557.00
Total Rebate Amount:	\$40,877.00

The information contained herein is correct as at 11 Mar 2023

OK

Mercedes-Benz CLA-Class CLA180 AMG Line

Overview

[Insurance](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)

Price	\$99,000		
Depreciation 	\$17,430 /yr View models with similar depre	Reg Date	05-Apr-2018 (5yrs 15days COE left)
Mileage	65,000 km (13.1k /yr)	Manufactured 	2017
Road Tax 	\$740 /yr	Transmission	Auto
Dereg Value 	\$35,145 as of today (change)	OMV 	\$28,637
COE 	\$36,810	ARF 	\$22,092
Engine Cap	1,595 cc	Power	90.0 kW (120 bhp)
Curb Weight 	1,480 kg	No. of Owners 	3
Type of Vehicle	Luxury Sedan		