



Final Report

Estimate No. : **B1 65298**
Date Estimated : **13/03/2023**
Prepared By : **Han Kwan Yong**

Page No. :

- ESTIMATE REPAIR FOR -

Ang Kwee Goh
27 jalan haji salam

Singapore 468811

- ACCOUNT -

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SKM1859J	WBA5A32010D334898	28/01/2014	520iA	82275

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper include carrying out necessary repairs caused by the accident	850.00		850.00
To respray rear bumper	986.00		986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function	168.00		168.00
To check electrical wiring system and lightings at the rear section for proper function	168.00		168.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PRIMED (PDC)	1,616.00	1.00	0.00	1,616.00

SUPPLEMENTARY ITEMS

Total Labour :	2,252.00
Total Parts :	1,616.00
Total Labour & Parts (before GST) :	3,868.00
Deduction for Excess :	
Total Repair Costs less Excess:	3,868.00
GST @8%:	309.44
Grand Total :	4,177.44

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
Co Reg No. 197401559W

